

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLR6738D	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/0142/2021	YEAR: 24-AUG-2017
ENGINE NO: FB20YA88854	CHASSIS NO: JF1SJ5KC5JG097379
DOA: 04/07/2021	TOA: 1255HRS
TYPE OF CLAIM: TP CLAIM	INS COMPANY: MS FIRST CAPITAL INSURANCE

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER & BEAM 560	\$2240.00 ✓
2.	RESPRAY FRONT BUMPER & BEAM 420	\$1680.00 ✓
3.	WHEEL ALIGNMENT	\$171.00
4.	FAULT DIAGNOSTIC	\$280.00
5.	LTA INSPECTION FOR OPC	\$120.00
6.	TO CONDUCT FRONT LIGHTING TEST	\$50.00
7.	TO CONDUCT FRONT PROTECTANT COATING	\$500.00
8.	TO CONDUCT FRNT ANTI RUST COATING	\$580.00
9.	SUNDRIES	\$100.00
10.	REMOVE / REFIX FRT HEADLAMP WASHER & PIPING	\$150.00
	Total Labour	\$5871.00

560
420
X
X
X
X
X
X
X
X
X
1100

DATE APPROVAL:	30/8/2021
TIME APPROVAL:	3pm
SURVEY BY:	Guo Qiang
HP / EMAIL:	82880282 / Guo.Qiang@lkkauto.com
BEFORE PAINT:	Yes
DAYS GIVEN:	3 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be surveyed and is subject to final approval by Insurance Company

Acknowledged by Repairer
Signature:
Date:

PO # QUOTATION:
SLR6738D

Account #: ESTIMATE

Date: 2021-07-06

Dealer Information	Customer Information
Name:	Name:
Address:	Address:
Phone:	Phone:
Fax:	Email:
Contact: MIE/PARTS/MR NG/67038175	Contact:

Vehicle Information
VIN: JF1SJ5KC5JG097379 Vehicle: 2018 > FORESTER(JF1,2) (S13)

Part No.	Description	Qty	Unit Price	Price
57709SG030	BUMPER FACE-FRONT <i>cut</i>	01	594.00	594.00 ✓
57722SG020	ENERGY ABSORBER-FRONT BUMPER <i>X NN</i>	01	126.00	126.00 ✓
57707SG000	BRACKET-FRONT BUMPER CORNER,RIGHT <i>X NN</i>	01	36.00	36.00
57707SG010	BRACKET-FRONT BUMPER CORNER,LEFT <i>X NN</i>	01	36.00	36.00
57707SG020	BRACKET-FRONT BUMPER SIDE,RIGHT <i>X NN</i>	01	12.60	12.60
57707SG030	BRACKET-FRONT BUMPER SIDE,LEFT <i>X NN</i>	01	12.60	12.60
57708SG010A	MOLDING-FRONT BUMPER LEFT <i>cut NN</i>	01	43.20	43.20
57711SG0009P	BACK BEAM COMPLETE-FRONT <i>X NN</i>	01	288.00	288.00
57731SG220	COVER-FRONT BUMPER <i>X NN</i>	01	4.40	4.40
57780SG010	PACKING-BUMPER,RIGHT <i>X NN</i>	01	9.00	9.00
57780SG020	PACKING-BUMPER,LEFT <i>X NN</i>	01	9.00	9.00
53029SG0019P	PANEL COMPLETE-RADIATOR <i>X NN</i>	01	360.00	360.00
84927SG030A	BRACKET-FOG LIGHT FRONT LEFT <i>X NN</i>	01	19.80	19.80

Labor Hours:

Labor Rate:

Labor:

Currency:

594

Shipping Method:

Shipping:

-20%: 475.2

Subtotal: 1,550.60

Tax Rate:

7.00

Tax:

108.54

1620.2

Total:

1,659.14

Dealer Message: