

GBC61435 2013 April
 TP China. Toyota Dyna 2982 CC
 Denise. JTFAT35YXOK202190

Front Number Plate.	Bent	30(SN) ✓
Front Bumper.	Bent	589.40 ✓
Front Bumper Bracket x 02	Bent	225.1 x 2 = 450.20 ✓
Front Grille	Missing	587.20 ✓
Front Grille Clips	new	20(SN) ✓
Front Grille Logo	Missing	86.90 ✓
Headlamp x 02	crackd	681.2 x 2 = 1362.40 ✓
Front Panel	Distorted	1019.30 ✓
Front Corner Panel x 02	RH Distorted	258.2 x 2 = 516.40 ✓
Front Panel Top Moulding	crackd	266.40 ✓
Front Panel Top Moulding (Side) x 02	RH Missing	122.70 122.7 x 2 = 245.40 ✓
Wiper Panel	Distorted.	418.90 ✓
Wiper Panel Side Cover x 02	RH crackd	212.70 212.7 x 2 = 425.40 ✓
Front Windscreen	Shattered	1288.30 ✓
Front Windscreen Moulding.	} New	285.10 ✓
Front Windscreen Sealant.		60(SN) ✓

GBC6143S.

Wiper Arm x 02	Bent	115 x 2 = 230. ✓
Wiper Blade x 02	Cd	35 x 2 = 70. ✓
Wiper Nozzle x 02.	RH could	68.5 x 2 = 137 / 68.50.
Wiper motor	Damaged	591.70 ✓
Wiper linkage.	Bent	387.70 ✓
FRP Bracket	14	26(SW) ✓
Dashboard.	Deformed	985.20 ✓
Dashboard Reinforcement.	Bent	635. ✓
Centre Console Cover.	could	349.20 ✓
Glove Box	could	298.40 ✓
Speedometer	{ NP New	1035.40 ✗
Steering Column Cover.		210.40 ✗
Air Con Blower.	{ could	1135.10 ✓
Air Con Evaporator.		1089.40 ✓
Brake Master Pump	{ NP New	367.10 ✗
Brake Booster Pump.		806.20 ✗
Brake Booster Pump Bracket.	Bent	225.50 ✓

GBC61438.

Air Can Condenser	{ HP MR	955.30	+
Radiator		1637.60	+
Engine Mounting x 02		$241.7 \times 2 = 483.40$	+
Front RH Door	Distorted	1310.80	-
Front RH Door Lock	Jammed	346.10	-
Front RH Door Weatherstripe	Wt	238.60	-
Front RH Door Inner Trim Board	caused	581.10	-
Front RH Door Inner Trim Board clips	m	30 (EW)	-
Front RH Door Hinge x 02	Bolt	$148.6 \times 2 = 297.20$	-
Front RH Door Check	Bolt	75.90	-
Front RH Door Glass	Shattered	408.10	-
Front RH Door Glass Outer Moulding	Del	115.10	-
Front RH Door Glass Regulator Gear	Repl	295.70	-
Front RH Door Glass Regulator Motor	see m	509	x
Front RH Door Pillar	Repl	764.20	+
Front RH Door Wing mirror	M m	313.80	+

GBC6143S.

Front RH Door Company Address Sticker. ^{New} 30(SN) ✓

Front RH Step Garnish. ^{NHMR} 241.10. ✓

Cabin Rear Pillar x 02. ^{Repis} 539.4 x 2 = 1078.80. ✓

Cabin Rear Windscreen. ^{shattered} 202.10. ✓

Cabin Rear Windscreen Moulding. ^{New} 85 ✓

Cabin Rear Windscreen Sealant. ^{NH} 60(SN) ✓

Cabin Lock Lever ^{Jammed} 398.50. ✓

1736760

13025.70.

SN: 256.

GBC 6143S.

Rear Number Plate.	} Bent	30(SN)	✓
Rear Number Plate Bracket.		155.10	✓
Rear Number Plate Lamp.	MP m	69.50	X
Rear Step Panel.	Bent	250(SN) 180(SN)	
Taillamp x 02	cracked	$251.8 \times 2 = 503.60.$	✓
Taillamp Panel x 02	Bent	$119.3 \times 2 = 238.60.$	✓
Stopper x 02	lost	$25 \times 2 = 50$ (SN)	✓
Stopper Bracket x 02.	Bent	$168.6 \times 2 = 337.20.$	✓
Tailgate	Distorted	1116.70	✓
Tailgate Hinge x 04.	Bent	$50.5 \times 4 = 202.$	✓
Tailgate Side Lock x 02	Bent.	$160.5 \times 2 = 321.$	✓
Tailgate Side Lock Latch x 02	Bent	$45 \times 2 = 90.$	✓
Tailgate Lower Panel.	Dented	485.90	✓
Toyota Sticker.	} New	176.50	✓
70km/h Sticker		10(SN)	✓
13 Pax Sticker.		10(SN)	✓

GB06143S.

Reverse Sensor Damaged ~~280(SN)~~ 200(SN) +

Rear Exhaust Pipe. } NP 585.20. +

Rear Exhaust Mounting. } M 45.10 +

Rear Canopy Best ~~1000(SN)~~ 450(SN).

Side Gate x02 Reps 1865.2x2 = 3730.40. +

Side Gate Advertisement Sticker x02. New 280x2 = ~~560(SN)~~ 400(SN)

Spare Tyre Lock. NP M 366.10. +

Rear Deck Carrier Reps 5800(SN) +.

3626.60.

2719.95.

S.N: 1330

GB C 6143S.

Panel Beating (Front).

Spray Painting (Front)

Wiring (Front)

To spray tuft seat (Front).

To remove upholstery.

To remove dashboard.

To replace front windscreen.

To remove air con system and }
to top up air con gas }

To transfer door fittings.

To replace cabin rear windscreen.

~~2800~~. 1500.

~~2500~~. 1600.

~~100~~ 30.

~~280~~. 150

~~250~~ 120

~~350~~ 220

~~180~~ 120.

~~350~~ 200.

~~150~~ 80.

~~120~~ 80.

4100.

GBC6143S.

Panel Beating (Rear).	1200	800.
Spray Painting (Rear)	1800	1000.
Wiring (Rear).	100	30.
To spray tuff coat (Rear).	150	80.
To remove reverse sensor	100	50
To remove rear deck carrier	350	280.
To repair and straighten rear chassis member.	800	500
To remove rear canopy	250	180.
To remove exhaust pipe	150.	X.

54868.20

2920.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 24351.65.

L/S: 18K.

18 Days.