

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

Estimate Repair List

12 July 2021

HHTPClaims21-46

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Attn: Motor Claims Department

ACCIDENT INVOLVING SMR 7794 Y& GBD 980 B ON 03/07/2021 ALONG SLIP ROAD GEYLANG EAST CENTRAL TO PAYA LEBAR ROAD AT ABOUT 1600 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SMR 7794 Y
Vehicle Make : TOYOTA
Vehicle Model : SIENTA HYBRID 7 SEATER 1.5X CVT
Vehicle Chassis No : NHP1707194579
Policy No : 5109921641-02-000336
Date of Accident : 03/07/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$	
1	1	Rear Bumper / <i>PL</i>		\$ 1,442.80	458.1
2	10	Rear Bumper Clips / <i>MC</i>	\$ 5.00	\$ 50.00	30
3	1	Rear Bumper Extension (Center) / <i>SCR</i>		\$ 643.40	171
4	1	Rear Bumper Extension (RH) / <i>SCR</i>		\$ 301.40	67.2
5	1	Rear Bumper Reflector (RH) <i>X NN</i>		\$ 118.20	
6	2	Rear Bumper Side Retainer (LH/RH) <i>X NN</i>	\$ 243.40	\$ 486.80	
7	1	Rear Tailgate / <i>Buc</i>		\$ 2,173.60	1086
8	1	Rear Tailgate Weatherstrip <i>X } NN</i>		\$ 316.16	
9	1	Rear Tailgate Lock <i>X</i>		\$ 472.72	
10	1	Rear Tailgate Emblem /		\$ 118.20	83.7
11	1	Rear Tailgate Logo (Hybrid Synergy) / <i>MC</i>		\$ 99.70	65.6
12	1	Rear Tailgate Lamp (RH) / <i>CRA</i>		\$ 624.72	281.55
13	1	Rear Tailgate Garnish <i>X } NN</i>		\$ 556.00	
14	1	Rear Tail Lamp (RH) <i>X } NN</i> <i>✓ CRA</i>		\$ 835.68	395.4
15	1	Rear Windscreen Moulding / <i>MC</i>		\$ 123.40	✓
16	1	Rear End Panel <i>X</i>		\$ 1,216.44	
17	1	Rear End Panel Outer <i>X</i>		\$ 756.00	
18	1	Rear End Panel Top Garnish <i>X } NN</i>		\$ 287.00	
				25%	\$ 10,622.22 2761.95
				Less 20%	\$ (2,124.44)
					\$ 8,497.78 2071.46
19	1	Rear Reverse Sensor / <i>DM</i>	NETT	\$ 200.00	✓
20	1	Sealant <i>X } NN</i> <i>✓ NEC</i>	NETT	\$ 40.00	✓
					\$ 800.00 <i>400</i>
					\$ 9,537.78

To cut & weld rear end panel. change rear bumper, rear tailgate
Knocking all area affected by accident

OOHRA Y RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

ACCIDENT INVOLVING SMR 7794 Y& GBD 980 B ON 03/07/2021 ALONG SLIP ROAD GEYLANG EAST CENTRAL TO PAYA LEBAR ROAD AT ABOUT 1600 HOURS

Estimate Repair List for vehicle SMA 3120 H - Toyota CHR

	Balance B/F	\$	9,537.78	
To perform wire checking		\$	50.00	30
To dismantle & refit rear windscreen		\$	120.00	✓
To dismantle & transfer rear tail gate mechanism fitting to new tail gate		\$	80.00	60
To dismantle & refit rear bumper sensor		\$	60.00	40
To spray rear end panel, rear bumper, rear tailgate and all affected area		\$	800.00	400
		\$	10,647.78	1050
	7% GST	\$	745.34	
	Total	\$	11,393.12	


Authorised by Claims Dept

4291.21

4 Days.

Unpsum repair

After repair photos.

Gmo Qiang - 82880282

Gmo Qiang @ lkkauto.com

15/7/2021

**AAK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: