

ASS. REC. BY: *marcus*

REF:

*CC4/A1621007421/URS3*ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMG 6410U

at Workshop m/s

ASIA motorsports

of

Insured:

SMX2886S

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$60k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

SB4D

Veh No:

SMG6410U

Yr Regn:

08/07/10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

*CAI**CAI*

Make:

mer Benz C180 c.c 1796

Colour:

silver

A/C: Insured / Std / NI / NA

Sp. Reading

215935

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2040492A377272

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

03/07/11

D.O.I.

8/7/11

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*Dep 7k.**up until 07-07-2030 @ 30199**14/7/11 confirmed 45 @ 9020 with AH long*

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) __ \$ + RS. __ \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Not Authorized
 NCR
 8/7/21
 2/s \$9000
 6 days.

SMG6410U Mercedes Benz C180

No	Qty	Part Description	Part Price
1	1	Rear bumper assy D/S 14/5-32	\$ 1,650.00
2	2	Rear bumper side retainer CNE 45x2290	\$ 122.00
3	2	Rear bumper bracket CNE 60x22-120	\$ 123.00
4	1	Rear bumper reinforcement Bmf	\$ 477.00
5	1	Rear bumper inner beam 11	\$ 279.00
6	1	Rear bumper inner garnish NS	\$ 255.00
7	1	Rear bumper tow cover C/W bumper	\$ 98.00
8	1	Rear bumper centre chrome moulding Bmf 166-02	\$ 195.00
9	1	Rear bumper left chrome moulding NCR 136	\$ 195.00
10	1	Rear bumper right chrome moulding NCR 136	\$ 195.00
11	1	Rear bootlid assy DO/Bu C 1578	\$ 1,793.00
12	1	Rear bootlid centre logo Bmf 90	\$ 126.00
13	1	Rear bootlid 'C180' emblem NCR 68	\$ 105.00
14	1	Rear bootlid 'CGI' emblem NCR 75	\$ 102.00
15	1	Rear bootlid 'cycle and carriage' emblem NCR 50	\$ 106.00
16	1	Rear bootlid lock mechanism Tm	\$ 282.00
17	1	Rear bootlid lock catch 11	\$ 96.00
18	1	Rear bootlid weatherstrip Tm 248.00	\$ 288.00
19	2	Rear bootlid rubber stopper 11	\$ 38.00
20	2	Rear bootlid hinges 11	\$ 440.00
21	1	Rear bootlid inner trim garnish 11	\$ 288.00
22	1	Rear bootlid outer chrome Bmf/Tm 266-50	\$ 330.00
23	1	Rear left taillamp CNE 585.21	\$ 875.00
24	1	Rear right taillamp CNE 585.21	\$ 875.00
25	1	Rear left taillamp garnish Tm 38.00	\$ 161.00
26	1	Rear right taillamp garnish Tm 38.00	\$ 161.00
27	1	Rear floor panel R	\$ 1,624.00
28	1	Rear spare tyre top cover worked	\$ 389.00
29	1	Rear left fender R	\$ 2,806.00
30	1	Rear right fender R	\$ 2,806.00
31	1	Rear left fender inner garnish Re/mugel 333	\$ 475.00
32	1	Rear right fender inner garnish RCR	\$ 475.00
33	1	Rear end lower panel Rads 915-40	\$ 984.00
34	1	Rear end lower panel top garnish CNE 115-00	\$ 197.00
35	1	Rear exhaust muffler assy R	\$ 1,495.00
36	2	Rear exhaust muffler rubber mounting 11	\$ 60.00
37	1	Rear windscreen glass moulding 11	\$ 288.00
38	1	Front left passenger headrest restraint CNE/Actual	\$ 755 985.00
39	1	Front right driver headrest restraint CNE/Actual	\$ 755 985.00
			\$ 23,224.00
less 10%			\$ 2,322.40
			\$ 20,901.60

9706-66
 102
 P- 873599
 S-N 300-00
 L- 228000

SMG6410U Mercedes Benz C180

No.	Qty	Part Description	Unit Price	Total Price
-----	-----	------------------	------------	-------------

Special Nett Items

1	10	Rear bumper clips <i>all</i>	\$	60.00 <i>SD</i>
2	1	Rear bumper lower spoiler <i>NF</i>	\$	1,280.00 <i>X</i>
3	1	Rear bumper lower spoiler sealant <i>NN</i>	\$	100.00 <i>X</i>
4	10	Rear bumper lower spoiler clips <i>NN</i>	\$	40.00 <i>X</i>
5	1	Rear left fender sealant <i>11</i>	\$	100.00 <i>X</i>
6	1	Rear right fender sealant <i>11</i>	\$	100.00 <i>X</i>
7	8	Rear left fender inner garnish clips <i>11</i>	\$	40.00 <i>X</i>
8	8	Rear right fender inner garnish clips <i>11</i>	\$	40.00 <i>X</i>
9	8	Rear bootlid inner trim garnish clips <i>11</i>	\$	40.00 <i>X</i>
10	1	Rear view camera <i>11</i>	\$	500.00 <i>X</i>
11	1	Rear floor panel insulator pad <i>11</i>	\$	140.00 <i>X</i>
12	1	Rear floor panel sealant <i>11</i>	\$	140.00 <i>X</i>
13	4	Rear bumper reverse sensor <i>shorted</i>	\$	1,200.00 <i>200 s/N</i>
14	1	Rear no plate with garnish <i>all</i>	\$	100.00 <i>X</i>
15	1	Rear end lower panel sealant <i>all</i>	\$	140.00 <i>50</i>
16	4	Rear end lower panel top garnish clips <i>11</i>	\$	30.00 <i>X</i>
17	4	Rear bootlid outer chrome clips <i>11</i>	\$	30.00 <i>X</i>
18	1	Rear windscreen glass sealant <i>11</i>	\$	100.00 <i>X</i>
			\$	4,180.00

Total parts
\$ 25,081.60

SMG6410U Mercedes Benz C180

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,400.00 <i>800</i>
2	To putty and spray painting rear portion.	\$ 1,400.00 <i>1100</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>30</i>
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 <i>60</i>
5	To remove and install rear exhaust muffler assy.	\$ 11 120.00 <i>X</i>
6	To remove and install rear fuel tank to facilitate the repair.	\$ 11 180.00 <i>X</i>
7	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 <i>80</i>
8	To apply anti rust proofing to rear affected area.	\$ 140.00 <i>60</i>
9	To remove and install rear bumper reverse sensor.	\$ 80.00 <i>50</i>
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 11 140.00 <i>X</i>
11	To remove and install rear view camera.	\$ 11 80.00 <i>X</i>
12	To remove and install front left passenger headrest restraint system.	\$ 280.00 <i>100</i>
13	To remove and install front right driver headrest restraint system.	\$ 280.00 <i>70</i>
14	To reset front air bag light.	\$ 11 250.00 <i>X</i>
15	Towing service.	\$ 11 100.00 <i>X</i>
Total labour :		\$ 4,720.00

Total parts : \$ 25,081.60

Total labour : \$ 4,720.00

Total repair cost : \$ 29,801.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: