



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC21002493/T1vf3e2-1 Date: 26/07/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 8152L	Veh. Inspected	GBG 4910L
Policy No.		Coverage (\$)	0.00
Claim No.	20/21/21/VC06/024236	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	07/07/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFAT35Y30K208686	Colour	BLUE
Odometer	131526 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	ROADIAN	6 mm
L/H Front Tyre	195 R15	ROADIAN	6 mm
R/H Rear Tyre	155 R12 (D)	ROADIAN	6/6 mm
L/H Rear Tyre	155 R12 (D)	ROADIAN	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/02/2021	Inspection Date	02/06/2021
Survey held at	QAS AUTO PTE LTD 3018A UBI ROAD 1 #01-23 SINGAPORE 408711		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	