

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 05/07/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBL3018T	VM20163813	
MODEL	: NISSAN NV200	Jaslin.	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 3-Jul-21
		TIME	: 12:30HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILGATE <i>dented</i>	1	\$ 2,155.30	\$ 2,155.30
2	REAR TAILGATE NISSAN LOGO	1	\$ 120.00	\$ 120.00
3	REAR TAILGATE NV200 EMBLEM	1	\$ 110.20	\$ 110.20
4	TAILGATE VANETTE EMBLEM	1	\$ 90.00	\$ 90.00
5	REAR TAILGATE LOCK <i>Repd</i>	1	\$ 320.50	\$ 320.50
6	REAR TAILGATE WINDSCREEN MOULDING <i>Nu</i>	1	\$ 180.20	\$ 180.20
7	REAR BUMPER <i>Deland</i>	1	\$ 650.30	\$ 650.30
8	REAR BUMPER SIDE RETAINER <i>Nu</i>	2	\$ 62.40	\$ 124.80
9	REAR BUMPER SPONGE <i>Replaced</i>	1	\$ 220.00	\$ 220.00
10	REAR END PANEL <i>Repl</i>	1	\$ 620.50	\$ 620.50

TOTAL PRICE \$ 4,591.80

LESS 10% \$ 459.18

SUB TOTAL PRICE \$ 4,132.62

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00
2	TAILGATE WINDSCREEN SEALANT <i>Nu</i>	1	\$ 100.00	\$ 100.00
3	TAILGATE 70KM/H STICKER <i>Nu</i>	1	\$ 20.00	\$ 20.00

4	TAILGATE 5PAX STICKER <i>new</i>	1	\$ 20.00	\$ 20.00	<i>10</i>
5	TAILGATE ADVESTMENT STICKER <i>new</i>	1	\$ 420.00	\$ 420.00	<i>250</i>
6	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
7	REVERSE SENSOR <i>Damaged</i>	1	\$ 200.00	\$ 200.00	<i>✓</i>
			<i>560</i> TOTAL	\$ 930.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>500</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>400</i>	
3	Tuff Coat	\$ 250.00	<i>40</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	TO REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 140.00	<i>120</i>	
6	ROMEVE & REINSTALL TAILGATE MECHANISM	\$ 100.00	<i>80</i>	
7	ROMEVE & REINSTALL REVERSE SENSOR	\$ 80.00	<i>50</i>	

TOTAL \$3,050.00

1220

TOTAL PARTS COST : \$ 5,062.62
TOTAL LABOUR COST : \$ 3,050.00
TOTAL REPAIR COST : \$ 8,112.62

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian L
1/s 06/07/21.

04 Days

total: 4762.15

1/s: 3.8K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: