JAS Auto Services

60 Jalan Lam Huat #05-06 Carros Centre, Singapore 737869 Tel: 6453 1967. Fax: 6457 3091 53255447K

India International Insurance M/s

64 Cecil St #04, #05, IOB Building

Singapore 049711

Fax: 6347 6100

Motor Claim Dept Attn:

Accident on 04/07/2021. Between SLM8286D AND CB8025E. (Your Insured) Re:

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned

accident damaged vehicle Third Party Claim.

	Parts 1. /	# 900100k8	Price
lpc	Front bumper de	AN MALOGER	\$900.80
1pc	Front bumper fog lamp cover Rh	4	\$160.50
1pc	Front bumper sensors 7.	2	\$350.00
1pc	Front bumper headlamp wiper Rh	Sonys	\$235.40
1pc	Front bumper headlamp wiper cover Rh C/	. b "	\$128.40
1pc	Front bumper retainer Rh 🗡	LIS	\$96.30
1pc	Front bumper tow cover 🗡	ا داداهم	\$32.10
1pc	Front bumper lower lip c	ישן סן סע	\$323.40
1pc	Headlamp Rh Su /	08/07/21	\$950.00
1pc	Front fender Rh	(01100	\$680.50
1pc	Bonnet 🗡	0	\$1,105.30
1pc	Intercooler piping 🗶	Resy after repair	\$420.50
1pc		700	
1pc		repair	
1pc		, I	

Total: \$5,383.20 Less: 10% \$538.32 \$4,844.88

Date:

8-Jul-21

11

Labour

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts. To putty & respray paint on the relevant repaired areas.

To rust proof affected areas where necessary.

Parts & Labour Total:

Your Faithfully

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: