

JAS Auto Services

60 Jalan Lam Huat #05-06 Carros Centre, Singapore 737869
Tel: 6453 1967. Fax: 6457 3091
53255447K

Date : 8-Jul-21

M/s India International Insurance
64 Cecil St #04, #05, IOB Building
Singapore 049711

Fax: 6347 6100

Attn: Motor Claim Dept

Re: Accident on 04/07/2021. Between SLM8286D AND CB8025E. (Your Insured)

Dear Sir,

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle **Third Party Claim**.

Parts	
1pc Front bumper	de/
1pc Front bumper fog lamp cover Rh	Xsu
1pc Front bumper sensors	? Xsu
1pc Front bumper headlamp wiper Rh	? Xsu
1pc Front bumper headlamp wiper cover Rh	cm/
1pc Front bumper retainer Rh	Xsu
1pc Front bumper tow cover	Xsu
1pc Front bumper lower lip	cm/
1pc Headlamp Rh	su/
1pc Front fender Rh	repair
1pc Bonnet	Xsu
1pc Intercooler piping	Xsu
1pc	
1pc	
1pc	

Pasul
#190010068
3 days
Ls
08/07/21
@14w

Price	
\$900.80	
\$160.50 X	
\$350.00 X	
\$235.40 X	
\$128.40	
\$96.30 X	
\$32.10 X	
\$323.40	
\$950.00	
\$680.50 X	
\$1,105.30 X	
\$420.50 X	

2072.34
1050.00
3122.34
20%
2497.87

Resy after repair

45-2,500
3 days

Total: \$5,383.20
Less: 10% \$538.32
\$4,844.88

Labour

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.
To putty & respray paint on the relevant repaired areas.
To rust proof affected areas where necessary.

\$800.00 500
\$800.00 550
\$90.00 Xsu

Parts & Labour Total: \$6,534.88

Your Faithfully,

JAS AUTO SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time:

2)

Report Format:
Cum I.B.I: (\$