

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20001691/KGA3Q2-1
Date: 13/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0000807_01
Claimant Vehicle No :	SHD9692C	Insured Vehicle No :	SLB4459G
Date of Loss:	20/01/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0000195

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9692C		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C35960
Reg. Date:	27/06/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU803082105
Colour:	Metallic Pearl White/Red	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,663.27	432.22	9,231.05	95.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,720.00	80.00	14,640.00	99.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,383.27	512.22	23,871.05	97.90
+ GST 7.00/7.00% (S\$)	1,706.83	35.86	1,670.97	97.90

Nett Amount (S\$)	26,090.10	548.08	25,542.02	97.90
+ Loss of Use (1.5 x S\$40.00/day) (S\$)		60.00		
+ Car Rental (1.5 x S\$113.40/day) (S\$)		170.10		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		785.63		
Global Sum Settlement (S\$)		750.00		

INSPECTION

Date of Assignment: 29/01/2020

Date Inspected: 29/01/2020

Estimated Period of Repair: 0.5 days

Inspected At:

Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2020)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9692C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Serviceable	442.60 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	*- FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	576.30 FL	*576.30 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
7	1		*REAR TAILGATE	Repair	1,147.80 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
10	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	650.30 FL	*- FL
11	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
12	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
13	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
14	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
15	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
16	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
17	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
18	1		*COVER ,FLOOR UNDER NO.1	Serviceable	175.10 FL	*- FL
19	1		*COVER ,FLOOR UNDER NO.2	Serviceable	241.90 FL	*- FL
20	1		*COVER REAR FLOOR	Serviceable	229.90 FL	*- FL
21	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
22	1		*SET REAR BUMPER CLIP	Serviceable	66.00 FS	*- FS
23	2		*REAR WINDSCREEN SEALANT	Serviceable	80.00 FS	*- FS
24	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	*- FS
25	1		*REAR WINDSCREEN INNER SPONGE SEAL	Serviceable	100.00 FS	*- FS
26	1		*REAR TAILGATE TOYOTA LOGO	Serviceable	47.00 FS	*- FS
27	1		*REAR TAILGATE WORDING PRIUS	Serviceable	52.90 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR TAILGATE WORDING HYBRID	Serviceable	53.50 FS	*- FS
29	1		*REAR TAILGATE STICKER TRANS-CAB	Serviceable	80.00 FS	*- FS
30	1		*REAR TAILGATE STICKER 6555-3333	Serviceable	80.00 FS	*- FS
31	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*- FS
32	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	*- FS
33	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*- FS
34	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
35	1		*REAR RH BUMPER RETAINER CLIP	Serviceable	25.00 FS	*- FS
36	1		*REAR LH BUMPER RETAINER CLIP	Serviceable	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,567.60	576.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,904.33	144.08
Total Parts (\$\$)	9,663.27	432.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
2	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
3	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
4	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
13	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	80.00
14	TO SUPPLY AND RE-DO REAR END PANEL INSULATION PADDING	New	380.00	0.00
Gross Labour Cost (\$\$)			14,720.00	80.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >