Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9692C

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

- wernicle iviodel:

Date of Accident :

Third Party Insurer:

Date of Registration:

PART

1	REAR	BUMPER

- 1 REAR BUMPER RE-INFORCEMENT
- 1 REAR BUMPER TOWING COVER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REAR BUMPER SIDE RETAINER LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REAR TAILGATE
- 1 REAR TAILGATE OUTER GARNISH
- 1 REAR TAILGATE WEATHERSTRIP
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 TAILLAMP LOWER RH
- 1 TAILLAMP UPPER RH
- 1 REAR BUMPER SIDE RH
- 1 REAR BUMPER SIDE LH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 COVER, DECK TRIM, REAR
- 1 COVER, FLOOR UNDER, NO 1
- 1 COVER, FLOOR UNDER, NO 2
- 1 COVER, REAR FLOOR

AAD2001-171

Not Nothern Resurry B4 paint

SHD 9692C

JTDKB3FU803082105

TOYOTA PRIUS

20.1.2020

Ш

2 9 JAN 2020

27/6/2019

LIST
\$ 1442.60 X
\$ SUL 332.70 ×
\$ 6 1540 V
\$ 14/h 57630.
\$ 5 11650
\$ 117.70
\$ N 1.147.80
\$ 925.60
\$ Jan 372 30
\$ 650.30
\$ 14 502.00 \x
\$ 451.80
\$ 12270/
\$ 123 70
\$ 502 00
\$ 54 443 3N
\$ SL 126.70
\$ Sh 17510
\$ 241.90
\$ 1 229 90

TOTAL \$	7,617.30
25% \$	1,904.33
\$	5,712.98

Trans-cab Auto Services Pte Ltd AAD2001-171 No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G SHD 9692C 700.00 1SET PARKING AID \$ 66.00 1SET REAR BUMPER CLIP 80.00 **REAR WINDSCREEN SEALANT** 100.00 1 WINDSCREEN MOULDING 100.00 REAR WINDSCREEN INNER SPONGE SEAL 47.00 **REAR TAILGATE TOYOTA LOGO** 52.90 REAR TAILGATE WORDING 'PRIUS' 1 53.50 REAR TAILGATE WORDING 'HYBRID' 1 80.00 Sir X REAR TAILGATE STICKER 'TRANS-CAB' 1 80.00 REAR TAILGATE STICKER '6555-3333' 1 100.00 REAR BUMPER PROTECTOR 1 1,879.40 REAR WHEEL RIM 350.00 **REAR TYRE 195/65/15** 211.50 REAR WHEEL RIM COVER 25.00 REAR RH BUMPER RETAINER CLIP 1 25.00 REAR LH BUMPER RETAINER CLIP 3,950.30 TOTAL \$ TOTAL PARTS \$ 9,663.28 LABOUR To transfer of Tailgate fittings, attachments and NA 170.00 X perform water seepage test. To transfer of Rear Bumper fittings, attachments and 170.00 X perform water seepage test. To transfer of rear end panel fittings, attachment and 5 170.00 X \$ perform water seepage test. To transfer of rear windscreen glass to facilitate 5 170.00 X \$ bodywork repair. 5 6,000.00 X Putty And Spray Painting Of The Affected Portion. S

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9692C

To check steering geometry and computer wheel alignment	\$	Na 220.00	<
To Rust-Proofing Of The Affected Areas.	\$	4 170.00	X
To reinstall rear bumper parking sensor.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To Check Electrical Lighting Concerned.	\$	5 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	801
To supply and re-do rear end panel insulation padding.	•	مد 380.00	Y
TOTAL	\$	14,720.00	-^
Over All Total	\$	24,383.28	
(PART-BY-PART) Repair Days		20 Tays	

LKK Auto Consultante hence notify the Repaire of the Coloring: • to resume process results of the • To digital than the money.

AAD2001-171