



Final Report

Estimate No. : **b1 58901**
Date Estimated : **07/07/2021**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -
KPW Engineering Pte Ltd
7 Gambas Crescent
#03-23

Singapore 757087

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK9289L	WBAJR32010BJ164	31/12/2018	530i	52264

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper including to knock out dented area caused by the accident	1,275.00	0.00	1,275.00
To respray front bumper and front right fender	1,826.00	0.00	1,826.00
To replace right headlight.	456.00	0.00	456.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	168.00	0.00	168.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,384.80	1.00	0.00	1,384.80
EXPANDING RIVET D=8MM	1.10	10.00	0.00	11.00
RH HEADLIGHT LED AHL HIGH (ICON LIG	4,887.60	1.00	0.00	4,887.60

SUPPLEMENTARY ITEMS

Total Labour :	4,043.00
Total Parts :	6,283.40
Total Labour & Parts :	10,326.40
Deduction for Excess :	
Total Repair Costs less Excess:	10,326.40
GST @7%:	722.85
Grand Total :	11,049.25

LOSS OF USE=\$120X 5 DAYS
GIA SEARCH FEE=\$2.00