

List

- 1) Front door - \$520
- 2) Door hinge x2 @ \$40 each - \$80
- 3) Front stepboard - \$105
- 4) Front corner panel - \$95
- 5) Front headlamp - \$310
- 6) Front bumper - \$200
- 7) Front bumper reinforcement - \$100
- 8) Air con ^{coil} ~~assy~~ - \$1165
- 9) Air con fan motor - \$705

\$3280

add 10% - \$328

\$3608

Total - \$3608

- \$80

- \$1530

\$5218

GST - \$365.26

\$5583.26

SN

- 10) Compressor oil - \$35
- 11) Refill Gas - \$45

\$80

Labour

- 12) To check wiring & lighting - \$30
- 13) To transfer door parts to new door - \$60
- 14) To dismantle & refix cabin with floor fitting & trimming - \$40
- 15) To remove & refix air con system - \$100
- 16) To spray paint accident portions - \$700
- 17) To dismantle & repair & replace accident area & parts - \$600

\$1530