



**Bedok Motor Engineering Pte Ltd**  
 30 Defu Lane 9 Singapore 539270  
<http://www.bedokmotor.com>  
[enquire@bedokmotor.com](mailto:enquire@bedokmotor.com)  
 +65 6286 3032

Estimate To Repair CB6868C YUTONG ZK6100H

Chassis No : LZYTBD63B1012944

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
1	1pc	Rear end panel	\$ 1,011.12
2	1pc	Rear end panel garnish reflector	\$ 799.79
3	1pc	Rear end body cross-member inner	\$ 647.72
4	1pc	Rear lamp lower L/h	\$ 499.72
5	1pc	Rear lamp centre L/h	\$ 332.12
6	1pc	Rear lamp upper L/h	\$ 301.32
7	1pc	Rear lamp panel	\$ 2,147.21
8	1pc	Side engine panel L/h	\$ 649.60
9	1pc	Side engine panel marker lamp	\$ 49.33
			\$ 6,437.93
		Less 10%	\$ 643.79
			\$ 5,794.14
		<u>LABOUR &amp; MISC CHARGE</u>	
1		To remove and refit interior fittings, fixtures, seats, trimmings and many others to facilitate repairs	\$ 1,500.00
2		To check electrical lightings concerned.	\$ 350.00
3		To cut off rear lamp panel and renew the same. To remove and renewal of the necessary parts, adjust and realign the same. To jack and pull out rear chassis body cross member and realign the same.	\$ 3,300.00
4		Putty and spray painting on the affected portion.	\$ 2,600.00
			\$ 7,750.00
		Total	\$ 13,544.14