

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0544/2021/GW
DATE : 6-Jul-21
WIP :

Veron.
~~\$17040.96~~ 13000

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 ATC BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHUE ZHENG YANG
ADDRESS : 19 ENG KONG ROAD
SINGAPORE 596144
TELEPHONE : HP +65 92322548
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210046282
VEHICLE NO : SMZ 6918 Y
MODEL CODE : AUDI E-TRON SPORTBACK AVANCED 50 QU
MODEL YEAR : 12/5/2021
ENGINE NO : -
CHASSIS NO : WAUZZZGE9MB030088
MILEAGE : 1710 KM
DATE IN : 3-Jul-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Jul-21
PLACE OF ACCIDENT : INTERSECTION OF TOH TUCK ROAD & TOH TUCK TERRACE

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 6918 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DEACTIVATE AND RE-ACTIVATE HIGH VOLTAGE SYSTEM FOR VEHICLE.	S/N \$	480.00	? X
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	250 ✓ 300
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	1000 ✓ 1200
5	TO RESPRAY FRONT BUMPER, RHS FRONT BUMPER, LOWER SPOILER, RHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,000.00	✓ 1800 550 x 2 = 1100 spoiler = 200 Air Tin 200 x 2 = 400
6	TO CARRY OUT PRE & POST DIAGNOSTIC CHECK.	S/N \$	384.00	✓
TOTAL LABOUR CHARGES		:	\$ <u>8,544.00</u>	1700

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 6918 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,724.00	✓ 2179.20
2	FRONT BUMPER FIXING PARTS <i>Not n</i>	1	\$ 631.00	X
3	PLASTIC FOAM STRIP <i>Not nec</i>	1	\$ 120.00	? X
4	FRONT BUMPER GRILLE LOWER CENTER <i>? Not n</i>	1	\$ 254.00	+
5	FRONT BUMPER GRILLE CENTER <i>? Not n</i>	1	\$ 153.00	+
6	FRONT BUMPER CLOSING ELEMENT CENTER <i>cracked</i>	1	\$ 222.00	+ ✓ 177.60
7	FRONT BUMPER CLOSING ELEMENT LOWER CENTER <i>cracked</i>	1	\$ 210.00	+
8	FRONT AIR INLET RH <i>cut Not nec</i>	1	\$ 91.00	? X
9	FRONT BUMPER REINFORCEMENT BEAM <i>Not n</i>	1	\$ 807.00	X
10	FRONT BUMPER SPOILER RH <i>cut</i>	1	\$ 157.00	✓ 131.60
11	FRONT BUMPER OUTER DUCT RH <i>cracked</i>	1	\$ 51.00	? ✓ 40.48
12	FRONT BUMPER INNER DUCT RH <i>? cracked</i>	1	\$ 39.00	? ✓ 31.20
13	FRONT BUMPER TRIM RH <i>Not n nec</i>	1	\$ 58.00	+ ✓ 46
14	FRONT BUMPER DUCT RH <i>cut</i>	1	\$ 120.00	? ✓ 95.60
15	FRONT BUMPER GUIDE SECTION RH <i>Dented</i>	1	\$ 44.00	✓ 35.12
16	FRONT SENSOR <i>Not nec</i>	1	\$ 1BC	? X
17	FRONT SENSOR SEAL RING <i>Not nec</i>	4	\$ 14.00	? X
18	FRONT FENDER RH <i>Dented</i>	1	\$ 2,201.00	✓ 1760.80
19	FRONT FENDER ATTACHMENT PARTS <i>Not n</i>	1	\$ 249.00	X
20	FRONT HEADLIGHT SEAL RH <i>Not nec</i>	1	\$ 53.00	? X
SUB TOTAL SPARE PARTS			\$ 8,198.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 6918 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET RH <i>? bent</i>	1	\$ 65.00	? ✓ 51.92
22	FRONT FENDER BRACKET RH FRONT	1	\$ 10.00	? X
23	FRONT FENDER BRACKET RH CENTRE	1	\$ 14.00	? X
24	FRONT FENDER SUPPORT ELEMENT RH	1	\$ 40.00	? X
25	FRONT FENDER INNER BRACKET RH	1	\$ 16.00	? X
26	FRONT WHEEL HOUSING LINER RH <i>Neu</i>	1	\$ 275.00	+
27	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Neu</i>	1	\$ 98.00	+
28	FRONT BUMPER SPOILER RH <i>? torn</i>	1	\$ 95.00	? ✓ 75.60
29	FRONT BUMPER BRACKET RH <i>Not nec.</i>	1	\$ 77.00	? X
30	LED HEADLIGHT RH <i>Could</i>	1	\$ 8,142.00	✓ 6513.60
31	LED WITH HEAT SINK RH	1	\$ 1,231.00	+
32	LED HEADLIGHT POWER MODULE RH <i>Neu</i>	1	\$ 758.00	+
33	LED HEADLIGHT HOSE RH <i>Neu</i>	1	\$ 29.00	+
34	LIFT CLYLINER FOR HEADLIGHT WASHER SYSTEM <i>Neu</i>	1	\$ 236.00	+
35	HOSE FOR HEADLIGHT WASHER SYSTEM <i>Neu</i>	1	\$ 96.00	+
36	FRONT FENDER INSCRIPTION 'E-TRON' <i>Neu</i>	1	\$ 106.00	✓ 84.80
37	FRONT WHEEL COVER LH RH <i>Neu</i>	2	\$ 1,030.00	✓ 827.20
38	FRONT BUMPER COVER RH	1	\$ 102.00	? X
39	FRONT BUMPER COVER	1	\$ 105.00	? X
40	STICKER FOR WARNING SIGN <i>Neu</i>	1	\$ 19.00	+
41	SUNDRIES <i>Nec.</i>		\$ 300.00	? 18.48
TOTAL SPARE PARTS		:	\$ 21,042.00	
TOTAL LABOUR CHARGES		:	\$ 8,544.00	
GRAND TOTAL		:	\$ 29,586.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan Lij
SURVEYED DATE : 07/07/21.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, ~~05 Days~~ 06 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT