

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1621007449/up33

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBA960A

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

\$

462m

Vehicle: IN / OUT

Date:

Person Contacted:

have a/c

Veh No: GBA960A

Yr Regn: 02/04/07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

in freezer

Make:

Toyota Dyna c.c 2982

Colour:

silver A/C: Insured / Std / NI / NA

Sp. Reading:

962090 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35Y90300048

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215 BS

R:

155-212 Falken

SS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5-

mm

R/Bal.

5/5

mm

L/Bal.

5-

mm

L/Bal.

5/5

mm

D.O.A.

29/6/21

D.O.I.

8/7/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & ft.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

we call 01-02-2022 LIA @ 2739

still can renew we. net 961

2/2/21 4/587200 confirmed with Alan.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

Not Authorized
Racer
8/7/21
1/5 \$7200
Amphibious After 4pm
8 days.

VEHICLE No: GBA 960A

2PCS	TAILLAMPS @\$296.90	one 28x50x2=571	\$593.80	✓
2PCS	TAILLAMP BRACKETS @\$105.00	Surf	\$210.00	✓
1PC	REAR EXHAUST	11	\$488.20	X
1PC	REAR SPARE TYRE CHAIN & BRACKET	11	\$398.20	X
1PC	REAR LICENCE PLATE BRACKET	Surf 168.20	\$198.50	✓
807.55 s/n	1PC	FRONT PANEL	\$1,615.10	50% s/n
1PC	FRONT PANEL CENTRE BLACK GARNISH	SCR 266.20	\$366.50	✓
2PCS	FRONT CORNER PANELS @\$205.00	11	\$410.00	X
1PC	FRONT CORNER PANEL TOP BLACK GARNISH N/S	11	\$155.10	X
1PC	FRONT DYNA EMBLEM	11	\$85.00	✓
1PC	FRONT WINDSCREEN RUBBER	11	\$211.10	✓
1PC	FRONT TOP NOSE PANEL GARNISH	Surf	\$388.20	✓
1PC	FRONT GRILLE	one	\$675.10	✓
1PC	FRONT GRILLE LOGO	11 102.00	\$105.00	✓
2PCS	HEADLAMPS @\$905.10	one 783.10x2=1566.20	\$1,810.20	✓
244.10 s/n	1PC	FRONT BUMPER	\$488.20	50% s/n
1PC	FRONT CROSS MEMBER	R	\$655.50	X
1PC	FRONT CABIN CROSS MEMBER	11	\$850.10	X
1PC	AIR CON BLOWER	one	\$1,005.30	✓
1PC	AIR CON HEATER UNIT	11	\$1,650.00	X
1PC	AIR CON CONDENSER	11	\$1,220.20	X
1PC	FRONT DOOR N/S	11	\$1,715.10	X
1PC	DASHBOARD	11	\$845.20	X
		(252)	\$16,139.60	
	S.NETT			
1PC	REAR FREEZER BOX LOCK BAR O/S	2	\$380.00	X
1PC	REAR LICENCE PLATE	Surf	\$20.00	14 s/n
1PC	REAR STEP PANEL	Surf	\$180.00	✓
1PC	1500kg STICKER	11	\$80.00	X
1SET	REAR STOPPER	Damaged	\$200.00	✓
1SET	REAR REVERSE BUZZER	one	\$280.00	150
1PC	REAR END ALUMINIUM PLATE	Red 500	\$680.00	✓
1SET	ALUMINIUM RIVET	11	\$80.00	X
1PC	FRONT LICENCE PLATE	Surf	\$20.00	14 7 s/n 50% s/n

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR <i>burger</i>	\$80.00	40
TO DISMANTLE & REFIX REAR EXHAUST	\$80.00	X
TO REFILL AIR CON GAS	\$100.00	✓
TO DISMANTLE & REFIX FRONT WINDSCREEN	\$150.00	60
TO DISMANTLE & REFIX FRONT DASHBOARD	\$300.00	200
TO DISMANTLE & REPLACING AIR CON BLOWER	\$100.00	50
TO SPRAY RUST PROOFING	\$100.00	50
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00	1300
TO PUTTY & SPRAY PAINTING	\$1,800.00	1000
TOTAL	\$22,619.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-524830
 252
 P-793622
 S.N-2282'65
 L- 2830
 904887
 207
 7229.08