

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WVS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: SGW 4303X
at Workshop m/s: L1
of _____
Insured: GBC 8734M
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: \$ 9500
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 9 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT



Veh No: SGW 4303X Yr Regn: 18/7/07
Type: M.Caf / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover L
Truck / Trailer or (A)
Make: mazda 3 sp Lux c.c. 1598
Colour: purple A/C: Insured / Std / NI / NA
Sp. Reading: 98320 T/Radio: Insured / Std / NI / NA
Eng No: _____
C/No: JM6BK10 6270348935
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/55-R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or kapsen
Front: 6 mm Rear: 6 mm
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 7/7/21 D.O.I. 8/7/21
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Bot N/S
The U/C / Chassis frame / Body Structure affected due to collision.

17-7-2022 LTA \$4923
low mileage net \$4577
19/7/21 453 4550 confirmed with Alan.

red: 20768.4253;82%

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 9
Resurvey No. of Trip: _____

1) _____
2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS: _____
Photos _____
Others _____
TOTAL

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Submit to insurance not Adharm
 2/11
 8/7/21

FASTECH AUTO PTE LTD
 1 KAKI BUKIT AVE 6 #01-48
 S'PORE 417883

2/SG 4550
 take photo after open
 9 days.

VEHICLE No: SGW 4303X
 QTY PARTICULAR

AMOUNTS\$

LIST ITEM:

QTY	PARTICULAR	AMOUNTS\$
1PCS	REAR BUMPER <i>D/S</i>	\$1,062.50 ✓
1PCS	REAR BUMPER REINFORCEMENT <i>Bent</i>	\$491.80 ✓
2PCS	REAR BUMPER SIDE RETAINERS @34.30 <i>Sent</i>	\$68.60 ✓
2PCS	REAR BUMPER REFLECTORS @54.90 <i>11</i>	\$109.80 X
2PCS	REAR BUMPER SIDE BRACKETS @20.50 <i>11</i>	\$41.00 X
2PCS	REAR BUMPER SPLASH SHIELDS @62.60 <i>11</i>	\$125.20 X
1SETS	REAR BUMPER CLIPS <i>s/n</i>	\$50.00 ✓
1PCS	BOOTLID	\$1,026.70 ✓
2PCS	BOOTLID HINGES @113.80 <i>Buc 926.20</i>	\$227.60 ✓
2PCS	BOOTLID REFLECTORS @303.50 <i>CR</i>	\$607.00 X
2PCS	BOOTLID STOPPERS @10.50 <i>205.00 x 2 = 410</i>	\$21.00 X
1PCS	BOOTLID INNER TRIM <i>11</i>	\$224.10 X
1SET	BOOTLID INNER TRIM CLIPS <i>11</i>	\$50.00 X
1PCS	BOOTLID WEATHERSTRIPS <i>Tw</i>	\$130.60 ✓
1PCS	BOOTLID INNER LOCK <i>Bent</i>	\$164.50 ✓
1PCS	BOOTLID LOCK STRIKER <i>11</i>	\$112.90 X
1PCS	BOOTLID REAR LOGO <i>11</i>	\$65.80 ✓
1PCS	BOOTLID MAZDA EMBLEM <i>11</i>	\$36.00 ✓
1PCS	BOOTLID 3 EMBLEM <i>11</i>	\$30.50 ✓
1PCS	BOOTLID SKYACTIV EMBLEM <i>NF</i>	\$608.70 X
1PCS	BOOTLID HARNESS <i>11</i>	\$408.60 X
1PCS	REAR KEY TRANSMITTER ANTENNA <i>11</i>	\$216.00 X
1PCS	REAR KEY TRANSMITTER ANTENNA CORD <i>11</i>	\$164.90 X
1SET	REAR LICENSE PLATE LAMP <i>11</i>	\$144.40 X
1PCS	REAR END PANEL <i>11</i>	\$395.30 ✓
1PCS	REAR END PANEL TOP GARNISH <i>Tw</i>	\$266.50 ✓
1PCS	REAR FLOOR PANEL <i>R</i>	\$2,221.00 X
1PCS	REAR FLOOR PANEL TOP BOARD <i>11</i>	\$605.30 X
2PCS	TAILLAMPS @941.30 <i>CR</i>	\$1,882.60 ✓
2PCS	REAR FENDERS @924.00 <i>Body 100/200</i>	\$1,848.00 ✓
2PCS	REAR FENDERS INNER TRIMS @285.30 <i>11</i>	\$570.60 X
1PCS	REAR EXHAUST <i>R</i>	\$952.40 X
2PCS	REAR EXHAUST MOUNTINGS @45.00 <i>11</i>	\$90.00 X
2PCS	TAILLAMP HOUSING PANELS @164.00 <i>R</i>	\$328.00 X
1PC	REAR WINDSCREEN <i>shattered 850.20</i>	\$1,288.20 ✓
1PC	REAR WINDSCREEN MOULDING <i>11</i>	\$85.20 ✓
1PC	FRONT BUMPER <i>11</i>	\$1,074.20 ✓
1PC	FRONT BUMPER REINFORCEMENT <i>R</i>	\$544.80 X
1PC	FRONT BUMPER SIDE RETAINER N/S <i>Bent</i>	\$45.50 ✓

202

1SET	FRONT BUMPER CLIPS	see s/n repeat nn	X \$50.00
1PC	FRONT FENDER N/S	n	\$431.00 X
1PC	FRONT FENDER INNER SHIELD N/S	nn	\$175.40 X
1SET	FRONT FENDER INNER SHIELD CLIPS N/S	nn	\$50.00 X
1PC	HEADLAMP N/S	cro	\$1,076.20 ✓
			\$20,168.40

S.NETT			
1SET	REAR BUMPER REVERSE SENSOR	showed	\$280.00 200
1PCS	REAR LICENSE PLATE	cro	\$50.00 20
1PCS	REAR END PANEL SEALANT	see	\$50.00 ✓
1PCS	REAR WINDSCREEN SEALANT	see	\$50.00 40
	TO CHECK WIRING		\$80.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00 50
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00 120
	TO TRANSFER BOOTLID COMPONENTS		\$120.00 60
	TO DISMANTLE & REPLACING REVERSE CAMERA	nn	\$100.00 X
	TO SPRAY RUST PROOFING		\$120.00 ✓
	TO DISMANTLE & REFIX REAR EXHAUST	nn	\$120.00 X
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS		\$2,000.00 1800
	TO PUTTY & SPRAY PAINTING		\$1,800.00 1600
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY		\$150.00 X
	TOATL		\$25,318.40

11010.2
 207
 8808.16
 12898.16

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: