

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 7-Jul-21

INSURANCE: FCI

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 8990Y

Description	Qty	List Price	Amount
Rear Door (RH) <i>Repair</i>	1	\$ 1,789.90	\$ 1,789.90
Rear Bumper <i>Demol</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Centre Moulding Assy <i>Cut</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>HH</i>	1	\$ 47.50	\$ 47.50
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (RH) <i>broken</i>	1	\$ 85.80	\$ 85.80
Rear Bumper Cover Clips <i>plc</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>HH</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(RH) <i>HH HH</i>	1	\$ 123.10	\$ 123.10
Rear Bumper Rear Hook <i>HH</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(RH) <i>HH</i>	1	\$ 82.90	\$ 82.90
Tail Lamp(RH) <i>broken</i>	1	\$ 870.40	\$ 870.40
Tail Lamp Quarter Panel(RH) <i>HH</i>	1	\$ 208.90	\$ 208.90
Rear Panel <i>HH</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>HH</i>	1	\$ 346.80	\$ 346.80
Panel Assy-Rear Floor Side (RH) <i>HH</i>	1	\$ 39.40	\$ 39.40
Rear tray tools box LH <i>HH</i>	1	\$ 693.20	\$ 693.20
Rear Fender(RH) <i>Demol</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Fender Inner Panel (RH) <i>HH</i>	1	\$ 1,406.20	\$ 1,406.20
Rear Fender SHIELD REAR PIECE (RH) <i>HH</i>	1	\$ 173.60	\$ 173.60
Rear Fender SHIELD Frt Piece (RH) <i>HH</i>	1	\$ 165.50	\$ 165.50
Rear Fender Corner inner upper garnish (RH) <i>HH</i>	1	\$ 486.70	\$ 486.70
Rear Fender Air-Duct (RH) <i>demol</i>	1	\$ 87.30	\$ 87.30
Rear Fender Trim Board (RH) <i>HH</i>	1	\$ 788.75	\$ 788.75
REAR FENDER TRIM BOARD TOP GARNISH (RH) <i>HH</i>	1	\$ 167.90	\$ 167.90
Assy BSD Blind Spot Radar (RH) <i>st bracket- photo</i>	1	\$ 1,625.00	\$ 1,625.00
Wiring Harness BWS Ext <i>HH</i>	1	\$ 988.90	\$ 988.90
Rear Tyre Rim (RH) <i>2 destroyed</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hub-Cap (RH) <i>cut</i>	1	\$ 346.40	\$ 346.40
Rear Wheelbearing & Hub assy <i>2 Demol</i>	1	\$ 554.00	\$ 554.00
Rear Trailing Arm(RH) <i>2 destroyed</i>	1	\$ 265.40	\$ 265.40
Rear Assist (RH) <i>2 destroyed</i>	1	\$ 227.90	\$ 227.90
Rear shock Absorber(RH) <i>2 destroyed</i>	1	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (RH) <i>HH</i>	1	\$ 133.10	\$ 133.10
Rear Absorber stopper (RH) <i>HH</i>	1	\$ 137.60	\$ 137.60
Rear Absorber Cover (RH) <i>HH</i>	1	\$ 175.60	\$ 175.60
Rear Crossmember <i>HH</i>	1	\$ 1,468.70	\$ 1,468.70
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30
Stabilizer Link (RH) <i>HH</i>	1	\$ 147.30	\$ 147.30
Rear Upper Arm(RH) <i>2 destroyed</i>	1	\$ 239.50	\$ 239.50
Rear Lower Arm(RH) <i>2 destroyed</i>	1	\$ 393.10	\$ 393.10
Rear Knuckle Arm (RH) <i>2 destroyed</i>	1	\$ 538.10	\$ 538.10

SUB TOTAL				\$ 20,135.95
LESS 20%				\$ 4,027.19
DISCOUNTED TOTAL				\$ 16,108.76
Rear Door Advertisement Logo (RH) HCU	SN	1	\$ 100.00	\$ 100.00
Rear Door Tel No.Sticker(RH) HCU HF	SN	1	\$ 10.00	\$ 10.00
Rear Door Comfortdelgro & Apps Sticker(RH) HCU	SN	1	\$ 80.00	\$ 80.00
Rear Bumper Advertisement Logo HCU	SN	1	\$ 50.00	\$ 50.00
Rear Bumper Rubber Mat HCU	SN	1	\$ 50.00	\$ 50.00
Rear Fender Advertisement Logo (RH) HCU	SN	1	\$ 100.00	\$ 100.00
Rear Tyre(RH) HU	SN	1	\$ 216.00	\$ 216.00
SUB TOTAL				\$ 606.00
Labour Charge				
Panel Beating		1	\$1,600.00	\$1,600.00
Spray Painting Charge		1	\$1,400.00	\$1,400.00
Wiring Charge		1	\$100.00	\$100.00
Tuff Kote		1	\$100.00	\$100.00
Towing Charge		1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00
Re-set Rear ABS System		1	\$400.00	\$400.00
Remove/Refix Fuel Tank		1	\$80.00	\$80.00
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00
Re-set Rear Power Window System		1	\$200.00	\$200.00
Four Wheel Alignment		1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor		1	\$550.00	\$550.00
TOTAL LABOUR				\$6,010.00
ESTIMATE TOTAL				\$ 22,724.76
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance				

09/07/2021 @ 17:00h

WAT Antwerp

H/Sme

6 days.

Yan

LKK Auto

P / P 9660-84

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
--