

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Jul 2021)
Parts: N/A VOLKSWAGEN TIGUAN 2.0 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJT4077D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*565.00 F
2	1		*1 PC REAR LOWER BUMPER	0.00	0.00	*198.00 F
3	1		*1 PC REAR BUMPER LH REFLECTOR	0.00	0.00	*29.00 F
4	1		*1 PC REAR BUMPER REINFORCEMENT	0.00	0.00	*370.00 F
5	1		*1 PC REAR BUMPER LH SIDE RETAINER	0.00	0.00	*30.00 F
6	1		*1 PC TAILGATE EMBLE, - TIGUAN	0.00	0.00	*76.00 F
7	1		*1 PC TAILGATE EMBLEM- 200/TSI	0.00	0.00	*66.00 F
8	1		*1 PC REAR BUMPER LOGO	0.00	0.00	*80.00 F
9	1		*1 PC REAR LH FENDER WHEEL ARP GARNISH	0.00	0.00	*290.00 F
Total Parts (S\$)						1,704.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	1) TO REMOVE AND REFIX REAR BUMPER, LOWER BUMPER & ATTACHMENTS, TAILALMP, REAR LH WHEEL ARCH GARNISH, KNOCK AND REPAIR REAR PANEL & RE-ALIGN TAILGATE TO SAME	New	500.00
2	2) TO PUTTY AND RESPRAY ON REAR BUMPER & ATTACHMENTS, TAILGATE, REAR LH FENDER, REAR PANEL AND ALL AFFECTED AREAS	New	700.00
Gross Labour Cost (S\$)			1,200.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11/2/2018 @ 1600h