



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120		Ref: CS3/AIG21005570/Bvf3e2-1 Date: 27/07/2021  Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLQ 7432J	Veh. Inspected	SLR 430E
Policy No.	1700030505	Coverage (\$)	0.00
Claim No.	5323674857SG	Excess (\$)	0.00
Assign From	SALIHA SYED YUSOF	Assign Date	08/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA SHUTTLE 1.5G	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81007687	Colour	BLACK
Odometer	67638 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	HABILEAD	5 mm
L/H Front Tyre	195/55 R15	HABILEAD	5 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	18/04/2021	Inspection Date	07/05/2021
Survey held at	YAP MOTOR SERVICE PTE LTD BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	