



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN KOK KIANG Reg No/Reg Date SFH3399S / 31/03/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5676707 Engine No G4FGGH653885 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/07/2021/ 09:07	BLE	261 / Edwin Caina	35774			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800 2400.00
RENEW FR BUMPER , FR SUPPORT & BONNET					2 X 494			
REPAIR LHF FENDER , LHF A PILLAR , RHF FENDER & RHF A PILLAR								2100.00 ✓
E PNT98000								
RESPRAY FR BUMPER , BONNET , LHF FENDER , LHF A PILLAR , RHF FENDER & RHF A PILLAR					6 X 350			100.00
E PNT88000								80.00
REMOVE & REFIT AC COND & RADIATOR								
M SUNDRY								30.00 ✓
TOP UP AC GAS								
A 54900099								120.00 ✓
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								240.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								270 280.00
RENEW FR WINDSCREEN GLASS								
M SUNDRY								80.00 ✓
INSTALL FR WINDSCREEN SOLAR FILM								
M SUNDRY								50.00
SUPPLY FR WINDSCREEN SEALANT								
M SUNDRY								40 80.00
SUPPLY FR NUMBER PLATE WITH CASING								
M SUNDRY								40 60.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								20 30.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								
Sundries								
M LAMP ASSY-HEAD,LH					1.00	1707.00	20.00	1365.60
M LAMP ASSY-HEAD,RH					1.00	1707.00	20.00	1365.60
M PANEL ASSY-HOOD					1.00	1384.00	20.00	1107.20
M HINGE ASSY-HOOD,LH					1.00	34.00	20.00	27.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for replacement of windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN KOK KIANG Reg No/Reg Date SFH3399S / 31/03/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5676707 Engine No G4FGGH653885 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/07/2021/ 09:07	BLE	261 / Edwin Caina	35774			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HINGE ASSY-HOOD,RH	BT			1.00	34.00	20.00	27.20
M	CARRIER ASSY-FRONT END MODULE	?			1.00	675.00	20.00	540.00
M	COVER-FR BUMPER	00			1.00	633.00	20.00	506.40
M	CAP-FRONT HOOK	X			1.00	9.00	20.00	7.20
M	MOULDING-FRT BPR LICENSE PLATE	X			1.00	18.00	20.00	14.40
M	LIP ASSY-FRONT BUMPER	X			1.00	55.00	20.00	44.00
M	GRILLE ASSY-RADIATOR	BR			1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE,UPR	CRU			1.00	54.00	20.00	43.20
M	STRIP ASSY-FR BUMPER UPR	CAT			1.00	29.00	20.00	23.20
M	MOULDING-FRONT BUMPER A/INTAKE	X			1.00	91.00	20.00	72.80
M	ABSORBER-FRONT BUMPER ENERGY	X			1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	X			1.00	114.00	20.00	91.20
M	RAIL ASSY-FR BUMPER	X			1.00	496.00	20.00	396.80
M	BRACKET-FR BUMPER SIDE MTG,LH	X			1.00	13.00	20.00	10.40
M	BRACKET-FR BUMPER SIDE MTG,RH				1.00	13.00	20.00	10.40
M	WIRING HARNESS-FR BUMPER	X			1.00	237.00	20.00	189.60
M	ULTRASONIC SENSOR ASSY-P.A.S	X			4.00	177.00	20.00	566.40
M	ORNAMENT-KIA NO.115	ACC			1.00	32.00	20.00	25.60
M	GLASS-WINDSHIELD	BR			1.00	956.00	20.00	764.80
M	MOULDING-WINDSHIELD GLASS	ACC			1.00	62.00	20.00	49.60
M	BRACKET, IU ADHESIVE	ACC			1.00	26.00	00.00	26.00
M	CONDENSER ASSY-COOLER	?			1.00	681.00	20.00	544.80
M	RADIATOR ASSY				1.00	546.00	20.00	436.80
M	BLOWER ASSY	?			1.00	623.00	20.00	498.40
M	LATCH ASSY-HOOD	?			1.00	65.00	20.00	52.00
M	PAD-HOOD INSULATING	X			1.00	141.00	20.00	112.80
M	CLIP-HOOD INSULATING PAD MTG	X			11.00	1.00	20.00	8.80
M	COOLANT (4L)	?			1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 9/7/21, 11:30am

DATE: 09-14-21

REMARKS: Extra - ?

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 9/7/21, 11-30am

DATE: 09-07-21

REMARKS: EXTRA - ?

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

Authorized signatory and Company Stamp

Nett 14,928.02
 7% GST on 14928.02 1044.96
Total Payable 15,972.98

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.