

ASS. REC. BY:

Steve

CS/AIG 2100 7477/ EV F3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 2100505876

Claims No. 3142789401SG

Sum Insured:

Excess:


500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Other

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng. No:

Ch. No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brakes: In order / Jammed / Locked / Burnt or

Mod: Nil / B. Rim / STD. Rim or

Tyre Size:

F:

R:

B3 / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

NV-548
PV-42,917
NV-11,083

9/9/21 Final fig \$10,252.80 confirmed by email (Red 5104.02, 33%)

Date/Time, File, Pass to:

: Prel. Report

: Final Report

Date/Time, File Return to:

10/9/21-Typist

Approved by: Merimen

Net Sum / I.B.J. \$10,252.80

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Inve (\$

: Weekend (\$

Survey Fee:

Transportation

S + RS \$

Phone

Others

TOTAL



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|---|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name /TAN KOK KIANG Reg No/Reg Date SFH3399S / 31/03/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5676707 Engine No G4FGGH653885 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim ABP AURORA BLACK / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|--|--------|-------------------|-----|-------------------|---------|------------|-------|-------------|
| LAX00000 | Credit | 09/07/2021/ 09:07 | BLE | 261 / Edwin Caina | 35774 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | | 800 2400.00 |
| RENEW FR BUMPER , FR SUPPORT & BONNET | | | | | 2 X 494 | | | |
| REPAIR LHF FENDER , LHF A PILLAR , RHF FENDER & RHF A PILLAR | | | | | | | | 2100.00 |
| E PNT98000 | | | | | | | | ? |
| RESPRAY FR BUMPER , BONNET , LHF FENDER , LHF A PILLAR , RHF FENDER & RHF A PILLAR | | | | | 6 X 350 | | | 100.00 |
| E PNT88000 | | | | | | | | ? |
| REMOVE & REFIT AC COND & RADIATOR | | | | | | | | 80.00 |
| M SUNDRY | | | | | | | | |
| TOP UP AC GAS | | | | | | | | 30.00 |
| A 54900099 | | | | | | | | |
| CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM | | | | | | | | 120.00 |
| A 10028901 | | | | | | | | |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | | | | | 240.00 |
| USING HI-SCAN PRO TEST | | | | | | | | |
| E PNT88000 | | | | | | | | 270 280.00 |
| RENEW FR WINDSCREEN GLASS | | | | | | | | |
| M SUNDRY | | | | | | | | 80.00 |
| INSTALL FR WINDSCREEN SOLAR FILM | | | | | | | | |
| M SUNDRY | | | | | | | | X 50.00 |
| SUPPLY FR WINDSCREEN SEALANT | | | | | | | | 40 80.00 |
| M SUNDRY | | | | | | | | 40 60.00 |
| SUPPLY FR NUMBER PLATE WITH CASING | | | | | | | | 20 30.00 |
| M SUNDRY | | | | | | | | |
| APPLY ANTI CORROSION ON AFFECTED AREAS | | | | | | | | |
| M SUNDRY | | | | | | | | |
| SUPPLY BODY PNL SEALANT | | | | | | | | |
| M SUNDRY | | | | | | | | |
| Sundries | | | | | 1.00 | 1707.00 | 20.00 | 1365.60 |
| M LAMP ASSY-HEAD,LH | / | | CUT | | 1.00 | 1707.00 | 20.00 | 1365.60 |
| M LAMP ASSY-HEAD,RH | / | | CUT | | 1.00 | 1384.00 | 20.00 | 1107.20 |
| M PANEL ASSY-HOOD | / | | CO | | 1.00 | 34.00 | 20.00 | 27.20 |
| M HINGE ASSY-HOOD,LH | / | | BT | | | | | |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for replacement of windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name /TAN KOK KIANG Reg No/Reg Date SFH3399S / 31/03/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5676707 Engine No G4FGGH653885 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim ABP AURORA BLACK / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|--------------------------------|-------------------|-----|-------------------|--------|------------|-------|--------|
| LAX00000 | Credit | 09/07/2021/ 09:07 | BLE | 261 / Edwin Caina | 35774 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M | HINGE ASSY-HOOD,RH | BT | | | 1.00 | 34.00 | 20.00 | 27.20 |
| M | CARRIER ASSY-FRONT END MODULE | | | | 1.00 | 675.00 | 20.00 | 540.00 |
| M | COVER-FR BUMPER | 00 | | | 1.00 | 633.00 | 20.00 | 506.40 |
| M | CAP-FRONT HOOK | X | | | 1.00 | 9.00 | 20.00 | 7.20 |
| M | MOULDING-FRT BPR LICENSE PLATE | X | | | 1.00 | 18.00 | 20.00 | 14.40 |
| M | LIP ASSY-FRONT BUMPER | X | | | 1.00 | 55.00 | 20.00 | 44.00 |
| M | GRILLE ASSY-RADIATOR | BR | | | 1.00 | 328.00 | 20.00 | 262.40 |
| M | GARNISH-RADIATOR GRILLE,UPR | CRU | | | 1.00 | 54.00 | 20.00 | 43.20 |
| M | STRIP ASSY-FR BUMPER UPR | CAT | | | 1.00 | 29.00 | 20.00 | 23.20 |
| M | MOULDING-FRONT BUMPER A/INTAKE | X | | | 1.00 | 91.00 | 20.00 | 72.80 |
| M | ABSORBER-FRONT BUMPER ENERGY | X | | | 1.00 | 84.00 | 20.00 | 67.20 |
| M | STIFFNER-FR BPR LWR | X | | | 1.00 | 114.00 | 20.00 | 91.20 |
| M | RAIL ASSY-FR BUMPER | X | | | 1.00 | 496.00 | 20.00 | 396.80 |
| M | BRACKET-FR BUMPER SIDE MTG,LH | X | | | 1.00 | 13.00 | 20.00 | 10.40 |
| M | BRACKET-FR BUMPER SIDE MTG,RH | | | | 1.00 | 13.00 | 20.00 | 10.40 |
| M | WIRING HARNESS-FR BUMPER | X | | | 1.00 | 237.00 | 20.00 | 189.60 |
| M | ULTRASONIC SENSOR ASSY-P.A.S | X | | | 4.00 | 177.00 | 20.00 | 566.40 |
| M | ORNAMENT-KIA NO.115 | NEC | | | 1.00 | 32.00 | 20.00 | 25.60 |
| M | GLASS-WINDSHIELD | BR | | | 1.00 | 956.00 | 20.00 | 764.80 |
| M | MOULDING-WINDSHIELD GLASS | NEC | | | 1.00 | 62.00 | 20.00 | 49.60 |
| M | BRACKET, IU ADHESIVE | NEC | | | 1.00 | 26.00 | 00.00 | 26.00 |
| M | CONDENSER ASSY-COOLER | X | | | 1.00 | 681.00 | 20.00 | 544.80 |
| M | RADIATOR ASSY | X | | | 1.00 | 546.00 | 20.00 | 436.80 |
| M | BLOWER ASSY | X | | | 1.00 | 623.00 | 20.00 | 498.40 |
| M | LATCH ASSY-HOOD | X | | | 1.00 | 65.00 | 20.00 | 52.00 |
| M | PAD-HOOD INSULATING | X | | | 1.00 | 141.00 | 20.00 | 112.80 |
| M | CLIP-HOOD INSULATING PAD MTG | X | | | 11.00 | 1.00 | 20.00 | 8.80 |
| M | COOLANT (4L) | X | | | 1.00 | 26.00 | 23.00 | 20.02 |

Estimate

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 9/7/21, 11:30am

DATE: 09-14-21

REMARKS: EXHIBIT - 1

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 9/7/21, 11-30am

DATE: 09-11-21

REMARKS: Excess - ?

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Nett 14,928.02
 7% GST on 14928.02 1044.96
Total Payable 15,972.98

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.