

(08/11/13) wef
ASS. REC. BY: marcus

REF: CS/CT121007478/Utc

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: STB 8433C
at Workshop m/s PAub
of _____
Insured: SKN 5889R
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$11k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STB 8433C Yr Regn: 25/1/08
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA/
Make: Toyota Rush c.c. 1495
Colour: black A/C: Insured / Std / NI / NA
Sp.Reading: 159459 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: J200ED 016640
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FALKEN

Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
L/Bal. 6 mm
D.O.A. 5/7/21 D.O.I. 15/7/21
Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>23/7/21</u> <u>27A # 6653 (see unt. 1 24-7-2023)</u>
	<u>noted 6347</u>
	<u>confirmed 4/5 \$2550 with Roy</u>

RED: 3983.18;60%

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS. \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I.: (\$ _____)

TOTAL

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST:201006949C RCB NO:201006949C

*Not Authorised
 2 late repairs
 15/7/21
 1/5 \$ 2530
 Take photo after repair
 3 days*

M/S : NICKLAUS LIM JOON LEK
 BLK 671B KLANG LANE #02-71
 SINGAPORE 212671

Estimate No: EST1507094
Date: 08 Jul 2021
Policy No: MT/00657759
Veh Reg No: SJB8433C
Make/Model: TOYOTA RUSH 1.5 A
Chassis No: J200E0016640
Engine No: 3SZ1916308
Reg. Date: 25/01/2008

ATTN: CHINA TAIPING
Your Ref No: TP 0721-6431
Claim Type: Third Party
Accident Date: 05/07/2021
TP Veh Reg No: SKN 5889 R

Estimate Repair Cost to Vehicle No :SJB8433C

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 TAILGATE <i>Body</i>	1,050.500	1 PC	1,050.50	✓
2 TAILGATE RUBBER <i>11</i>	225.5000	1 PCS	225.50	X
3 TAILGATE LOCK <i>11</i>	199.8000	1 PCS	199.80	X
4 TAILGATE RUSH LOGO <i>new</i>	79.8000	1 PCS	79.80	✓
5 REAR SPARE TYRE RIM <i>see</i>	2,190.300	1 PC	2,190.30	X
6 REAR SPARE TYRE COVER - INNER <i>one</i>	518.6000	1 PCS	518.60	✓
7 REAR SPARE TYRE BRACKET <i>Beif</i>	220.5000	1 PC	220.50	✓
8 REAR BUMPER <i>de</i>	780.3000	1 PC	780.30	✓
9 REAR BUMPER CLIPS <i>new</i>	5.5000	10 PC	55.00	✓
10 REAR BUMPER SIDE HOLDER - LH <i>11</i>	79.7000	1 PCS	79.70	X
11 REAR BUMPER SIDE HOLDER - RH <i>11</i>	79.7000	1 PCS	79.70	X
12 REAR BUMPER NUMBER PATE LAMP - RH/LH <i>11</i>	105.6000	2 PCS	211.20	X
			5,690.90	
	Less 25%		1,422.73	4,268.18
Special Net				
13 SEALANT <i>Rear windscreen new</i>	20.0000	2 PCS	40.00	✓
14 SPONGE TAPE <i>Rear windscreen new</i>	20.0000	1 PCS	20.00	✓
15 REAR BUMPER SENSOR <i>11</i>	220.0000	1 SET	220.00	X
16 REAR NUMBER PLATE WITH CASING <i>11</i>	35.0000	1 PC	35.00	X
			315.00	315.00
Labour				
17 TO KNOCK OUT DENTS, REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	400
18 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	500
19 TO TUFF-KOTE	100.0000	1 JOB	100.00	30
20 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
21 TO REMOVE, REFIT REAR GARNISH	80.0000	1 JOB	80.00	60
22 TO REMOVE, REFIT REAR BOOT GLASS	150.0000	1 JOB	150.00	120
			1,950.00	1,950.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : NICKLAUS LIM JOON LEK
BLK 671B KLANG LANE #02-71
SINGAPORE 212671

Estimate No: **EST1507094**
Date: 08 Jul 2021
Policy No: MT/00657759
Veh Reg No: **SJB8433C**
Make/Model: TOYOTA RUSH 1.5 A
Chassis No: J200E0016640
Engine No: 3SZ1916308
Reg. Date: 25/01/2008

ATTN: CHINA TAIPING
Your Ref No: TP 0721-6431
Claim Type: Third Party
Accident Date: 05/07/2021
TP Veh Reg No: SKN 5889 R

Estimate Repair Cost to Vehicle No :SJB8433C

Description	U/Price	Quantity	Price	Amount
			SS	SS
			Total	SS 6,533.18
			Add GST @ 7%	457.32
			Total Amount Payable	SS 6,990.50

TOTAL: SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED NINETY AND CENTS FIFTY ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P2704.7
252
P-202852
S-N-60
L-1130
3218.52
2574