

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Email: xinhuaworkshop@gmail.com

Reg : 201838521G

Vehicle Number : SLL 687 M

Vehicle Model : CHEVROLET ORLANDO

Accident Date : 06.07.2021

Original Reg Date : 13.02.2017

Date : 08.07.2021

Chassis : KL1YA7589HK609535

TP Ins. AXA INS

TP AXA

Justin.

ESTIMATE

1	FRT FENDER LH	Dented		\$ 1,243.00	✓
1	FRT FENDER BRACKET LH	Neu		\$ 128.00	+
1	FRT FENDER INNERSHIELD LH	Neu		\$ 268.00	+
1	FRT FENDER TOP GARNISH LH	Neu		\$ 88.00	+
1	FRT FENDER WHEELARCH GARNISH LH	Neu		\$ 152.00	✓
1	FRT ENGINE LOW SUBFRAME	2		\$ 2,775.00	+
1	FRT KNUCKLE ARM LH			\$ 417.00	+
1	FRT WHEEL BEARING LH	Neu		\$ 587.00	+
1	FRT LOW ARM LH			\$ 928.00	+
1	FRT SHOCK ABSORBER LH			\$ 443.00	+
1	FRT SHOCK ABSORBER TOP MOUNTING LH	Neu		\$ 132.00	+
1	FRT STABILIZER LINK LH	Neu		\$ 142.00	+
1	FRT RIM LH	Cut		\$ 898.00	✓
1	Frt LH Door	Dented.		\$ 1,700.00	✓
1	Frt LH Door Black Sticker	Neu		\$ 196.00	✓
1	Frt LH Door Protector	cut		\$ 151.00	✓
1	Frt LH Door Weatherstrip	Neu		\$ 253.00	+
1	Frt LH Door Glass Outer Moulding	Neu		\$ 247.00	+
1	Frt LH Wing Mirror Assy	Neu		\$ 1,081.00	+
1	RR LH Door	Dented		\$ 1,841.00	✓
1	RR LH Door Black Sticker, Front	3 neu		\$ 191.00	✓
1	RR LH Door Black Sticker, Rear			\$ 203.00	✓
1	RR LH Door Protector	cut		\$ 160.00	✓
1	RR LH Door Child Lock Warning Label	Neu		\$ 35.00	✓
1	LH Rocker Panel Garnish	Dented		\$ 291.00	✓
1	LH Rocker Panel Rubber Beading	Neu		\$ 113.00	+
1	RR Fender LH	Neu		\$ 2,017.00	+
1	RR Fender Wheelarch LH	Cut		\$ 152.00	✓

7213

6491.70

\$ 16,832.00

Less 10% \$ 1,683.20

\$ 15,148.80

Special Nett

1	1 pc	Frt Number Plate with Cover	Neu	\$ 65.00	+
2	10 pc	Frt Bumper Clip	Neu	\$ 50.00	+
3	10 pc	Frt Fender Inner Shield Clip	Neu	\$ 50.00	+

4	10 pc	fender protector clip <i>NHE m</i>		\$ 50.00	x
5	20 pc	door protector clip <i>NHE</i>		\$ 100.00	30
6	1 pc	Body Panel Joint Sealer <i>NHE m</i>		\$ 120.00	x

30

Labour charge

To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00	600
Carry out spray painting on accident affected area, FRT FENDER LH, FRT DOOR LH, RR DOOR LH, RR FENDER LH	\$ 1,000.00	600
To conduct anti rust of under carriage tuff coat	\$ 80.00	x
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	30
To remove and replace LHF under carriage parts	\$ 300.00	x
To conduct 4 wheel alignment	\$ 180.00	80
To conduct transfer front door mechanism to new door panel	\$ 200.00	80
To conduct transfer rear door mechanism to new door panel	\$ 200.00	80
To apply door sealant to door	\$ 120.00	x

1470

Total \$ 18,783.80

GST 7% \$ 1,314.87

Grand Total \$ 20,098.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
1/s 09/07/21

05 Days

total: 799.70

1/s: 6.3K