

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rasul  
hp 9010068

6-7 days

23/07/21 @ 1000

Resuy before paint



**SERVICE ESTIMATE**

90321 - C00001  
Mr Ong Tiong Guan  
27 Lynwood Grove

SL: SERVICE SALES - PC

GST Reg.No: M28920628X

Inv.No. . . : B&P 0 Page 1  
Inv.date. . : 01/07/2021  
WIP No. . . : 30678  
Veh.In/Out:  
\*Tel.No. . . : Mobile: 92206290  
Reg.No. . . : SLQ2554Z  
Reg.date . . : 30/06/2017  
Mileage . . : 0  
Chassis No: SAJAC12M8GPW01869

Singapore 358675

Closed by . . . . : Paul Ong Qing Yong  
Svc Consultant :  
Remarks . . . . . : Mr Ong Tiong Guan

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT LH DOOR, @1300	0	5000.00	0		5,000.00	S
	REPAIR REAR LH DOOR, LH REAR FENDER, REAR BUMPER, ETC					<del>3250</del>	
800	TO SPRAYPAINT ON FRT LH DOOR, REAR LH DOOR, @1000	0	4500.00	0		4,500.00	S
	REAR LH FENDER, REAR BUMPER, ETC					<del>4000</del>	
802	TO REMOVE, REFIT & TRANSFER FRT LH DOOR PARTS	0	500.00	0		500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
	DOOR PANEL FRT LH V5 bt ✓	1.0 EA	9890.70			9,890.70	S
	SEAL-DOOR ne ✓	1.0 EA	929.50			929.50	S
	SOUND DEADENING PAD ne ✓	1.0 EA	578.00			578.00	S
	BUMPER NUT XF ne ✓	15.0 EA	4.50			67.50	S

Gross Total. 22,086.70  
Net..... 22,086.70  
GST @ 7.0% 1,546.07  
Total..... 23,632.75  
Paid..... 0.00  
Please Pay.. 23,632.75

Labour Total 10,621.00  
Parts Total 11,465.70  
Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated