10/22/21, 2:41 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21007496/R1VCN2

22/10/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00003052101

Claimant Vehicle

SKZ1329D

Insured

SKH3453J

Vehicle No:

Date of Loss:

No:

20/06/2021

Nature of Claim: TP

No:

Odometer:

SNM21D203801/C02/TOHHS

121554 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKZ1329D Reg No:

K9KG657D008038 RENAULT GRAND SCENIC III, 1.5 DCI (A) Make & Model: Engine No: Reg. Date: 11/01/2016 (Man. Year: 2015) Chassis No: VF1JZ49BJ54183866

Colour: White

Engine Capacity: 1461 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/55R17 Rear Tyre Size: 205/55R17 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,618.00	1,761.30	1,856.70	51.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	510.00	210.00	29.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,338.00	2,271.30	2,066.70	47.64
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	4,338.00	1,800.00	2,538.00	58.51
+ GST 7.00/7.00% (S\$)	303.66	126.00	177.66	58.51
Nett Amount (S\$)	4,641.66	1,926.00	2,715.66	58.51

INSPECTION

Date of Assignment: 06/08/2021

BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08. 16/08/2021 Inspected At: Date Inspected:

SINGAPORE 159722

REPAIRER: MOVA AUTOMOTIVE PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

10/22/21, 2:41 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Oct 2021)

Parts: M1-MPV RENAULT GRAND SCENIC III 1.5 DCI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ1329D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	980.00 FL	*787.00 FL
2	1		*REAR BUMPER LOWER GARNISH (MATT BLACK)	Cut	690.00 FL	*430.00 FL
3	2		*REAR PARKING SENSOR CTR	Serviceable	560.00 FL	*- FL
4	1		*REAR BUMPER LAMP RH	Serviceable	260.00 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	750.00 FL	*660.00 FL
7	1		*REAR BUMPER CTR RETAINER	Serviceable	300.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	400.00 FL	*- FL
F=Fra	ınchise	part. L=ListIte	emDisc.	-		
				Sub Total (S\$)	4,020.00	1,957.00
	- List Item Discount on L Items 10.00/10.00% (S\$)		402.00	195.70		
				Total Parts (S\$)	3,618.00	1,761.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	<u>our Items</u>					
1	TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING	New	80.00	0.00		
2	TO INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION	New	80.00	60.00		
3	TO REMOVE & REPLACE DAMAGED ITEMS.REALIGN CONNECTION	New	280.00	250.00		
4	TO SPRAY PAINT ON REPAIRED AREAS	New	280.00	200.00		
	Gross Labour Cost (S\$)		720.00	510.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >