



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JACKSON LIM JEK SHENG (LIN YICHENG)	Cust No/Name	/JACKSON LIM JEK SHENG (LIN YICH
BLK 275D JURONG WEST STREET 25	Reg No/Reg Date	SGC5802X / 06/01/202
#13-67	Date In/Mileage	/ 0
SINGAPORE 644275	Chassis No	KNAF5416MK5052314
Contact No Mobile: 6583630363	Engine No	G4FGKH749375
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/07/2021/ 11:56	BLC	442 / CocoLu	35809			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1750.00
RENEW FRT BUMPER, FRT SUPPORT PANEL, BONNET REPAIR FRT FENDER RH & LH								1750.00
E PNT98000								100.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH								50.00
E PNT88000								30.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								120.00
M SUNDRY								100.00
FRT NUMBER PLATE WITH FRAME								80.00
A 90000001								40.00
CHECK WIRING & ELECTRICAL SYSTEM								20.00
A 10028901								100.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								80.00
USING HI-SCAN PRO TEST								20.00
E PNT88000								633.00
REMOVE & INSTALL PARKING SENSOR								485.00
M SUNDRY								328.00
TOP UP AIRCON GAS								38.00
M SUNDRY								303.00
APPLY SEALANT FOR ACCIDENT PORTION								303.00
M SUNDRY								216.00
Sundry								216.00
M	COVER-FR BUMPER				1.00	633.00	00.00	216.00
M	GRILLE-FRONT BUMPER				1.00	485.00	00.00	143.00
M	GRILLE ASSY-RADIATOR				1.00	328.00	00.00	143.00
M	GARNISH-RADIATOR GRILLE				1.00	38.00	00.00	84.00
M	LAMP ASSY-FRONT FOG,RH				1.00	303.00	00.00	114.00
M	LAMP ASSY-FRONT FOG,LH				1.00	303.00	00.00	
M	MOULDING-FRONT BUMPER,RH				1.00	216.00	00.00	
M	MOULDING-FRONT BUMPER,LH				1.00	216.00	00.00	
M	LAMP ASSY-SIDE REPEATER,RH				1.00	143.00	00.00	
M	LAMP ASSY-SIDE REPEATER,LH				1.00	143.00	00.00	
M	ABSORBER-FRONT BUMPER ENERGY				1.00	84.00	00.00	
M	STIFFNER-FR BPR LWR				1.00	114.00	00.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JACKSON LIM JEK SHENG (LIN YICHENG)	Cust No/Name	/JACKSON LIM JEK SHENG (LIN YICH)
BLK 275D JURONG WEST STREET 25	Reg No/Reg Date	SGC5802X / 06/01/202
#13-67	Date In/Mileage	/ 0
SINGAPORE 644275	Chassis No	KNAF5416MK5052314
Contact No Mobile: 6583630363	Engine No	G4FGKH749375
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	09/07/2021/ 11:56	BLC	442 / CocoLu	35809		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	ULTRASONIC SENSOR ASSY-P.A.S			1.00	163.00	00.00	163.00
M	BRACKET-FR BUMPER UPR SIDE MTG			1.00	22.00	00.00	22.00
M	BRACKET-FR BUMPER UPR SIDE MTG			1.00	22.00	00.00	22.00
M	PANEL ASSY-HOOD			1.00	1502.00	00.00	1502.00
M	BEAM COMPLETE-FR BUMPER			1.00	497.00	00.00	497.00
M	CARRIER ASSY-FRONT END MODULE			1.00	675.00	00.00	675.00
M	PAD-HOOD INSULATING			1.00	156.00	00.00	156.00
M	LATCH ASSY-HOOD			1.00	103.00	00.00	103.00
M	ORNAMENT-KIA NO.115			1.00	32.00	00.00	32.00
M	LAMP ASSY-HEAD,RH			1.00	2210.00	00.00	2210.00
M	LAMP ASSY-HEAD,LH			1.00	2210.00	00.00	2210.00
M	TUBE ASSY-SUCTION & LIQUID			1.00	462.00	00.00	462.00
M	HOSE-DISCHARGE			1.00	122.00	00.00	122.00
M	GUARD-AIR,RH			1.00	28.00	00.00	28.00
M	GUARD-AIR,LH			1.00	28.00	00.00	28.00
M	CONDENSER ASSY-COOLER			1.00	687.00	00.00	687.00
P	BRACKET ASSY-RADIATOR MTG,UPR			2.00	29.00	00.00	58.00
M	RADIATOR ASSY			1.00	646.00	00.00	646.00
P	INSULATOR-RADIATOR MTG,LWR			2.00	9.00	00.00	18.00
M	BLOWER ASSY			1.00	656.00	00.00	656.00

Confirm & accepted by

Nett 17,343.00
7% GST on 17343.00 1214.01
Total Payable 18,557.01

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.