

ASS. REC. BY:

REF:

PC2/21007503/ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

837,953/

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

Got BZ

12/7

11 Lmp

89450/

Conf

Veh No:

S/HO 323C

Yr Regn:

031 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c.

1995

Colour

M. White Red

A/C:

Insured / Std / NI / NA

Sp. Reading

79226P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1 ABL-5AUC 282614

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

8/7/21

D.O.I.

9/7/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD323C**AAD2107-034***Not Authenticated
C/Sing \$9450h*

Vehicle No.:

Chassis No.:

Vehicle Make:

09 JUL 2021

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD323C

VF1ABL15AUC282614

RENAULT

LATITUDE

08/07/2021

TOWER TRANSIT (FCI)

04/03/2016

PART**LIST**

1 BUMPER COVER REAR	\$	B ₁ 561.70	✓
1 BUMPER LOWER REAR	\$	B ₁ /D ₁ 411.90	✓
1 BUMPER REFLECTOR LH	\$	CM 16.60	✓
1 BUMPER REFLECTOR RH	\$	SL 16.60	X
1 BUMPER BRACKET CTR REAR	\$	SL 98.10	X
1 BUMPER BRACKET SIDE RH REAR	\$	D ₁ 82.10	✓
1 BUMPER RETAINER RH REAR	\$	SL 59.80	X
1 BUMPER BRACKET SIDE LH REAR	\$	D ₁ 80.80	✓
1 BUMPER RETAINER LH REAR	\$	D ₁ 54.20	✓
1 ABSORBER REAR	\$	NIP 217.30	X
1 BUMPER BEAM REAR	\$	B ₁ 547.80	✓
1 BUMPER BEAM BRACKET LH REAR	\$	M ₁ 114.50	✓
1 BUMPER BEAM BRACKET RH REAR	\$	N 114.50	X
1 OUTER PANEL REAR (End Panel)	\$	B ₁ 745.80	✓
1 OUTER PANEL REAR (End Panel)TRIM	\$	D ₁ 404.56	✓
1 SPARE WHEEL PANEL	\$	N 1,229.40	X
1 SPARE TYRE BOARD	\$	SL 680.90	X
1 TAILLAMP LH	\$	B ₁ 401.40	✓
1 TAILLAMP RH	\$	CM 401.40	✓
1 EXHAUST CAP REAR	\$	N 125.40	X
1 BOOT REAR	\$	B ₁ 1,677.20	✓
1 BOOT BADGE 'RENAULT'	\$	M ₁ 82.40	✓
1 BOOT BADGE	\$	M ₁ 95.80	✓
1 BOOT REFLECTOR LAMP LH	\$	CM 277.70	✓
1 BOOT REFLECTOR LAMP RH	\$	CM 277.70	✓
1 BOOT HINGE LH	\$	B ₁ 254.20	✓
1 BOOT HINGE RH	\$	N 254.20	X
1 BOOT STRUT LH	\$	SL 145.10	X

Trans-cab Auto Services Pte Ltd**AAD2107-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD323C

1 BOOT STRUT RH	\$	<i>sn</i> 145.10	<i>X</i>
1 BOOT LOCK	\$	<i>na</i> 246.60	<i>✓</i>
1 BOOT LOCK CATCH	\$	<i>DIY</i> 41.70	<i>✓</i>
1 BOOT FINISHER	\$	<i>Refurn</i> 344.70	<i>✓</i>
1 FENDER PANEL REAR LH	\$	<i>B1/Bn</i> 1,933.20	<i>✓</i>
1 WHEELARCH REAR LH	\$	<i>sn</i> 275.40	<i>X</i>
	\$	12,415.76	
10%	\$	1,241.58	
	\$	11,174.18	

Special Nett

1SET PARKING AID	\$	<i>Red/shot</i> 700.00	<i>400sn</i>
1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	<i>✓</i>
1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	<i>X</i>
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	<i>X</i>
1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00	<i>X</i>
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	<i>X</i>
1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00	<i>X</i>
1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	<i>✓</i>
1 EXHAUST MOUNTING REAR	\$	<i>sn</i> 17.82	<i>X</i>
1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i> 80.00	<i>30sn</i>
1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i> 80.00	<i>30sn</i>
1 LICENSE PLATE WITH HOLDER FR	\$	<i>na</i> 120.00	<i>45sn</i>
2 WINDSCREEN SEALANT	\$	<i>na</i> 150.00	<i>40sn</i>
1 WINDSCREEN MOULDING	\$	<i>na</i> 200.00	<i>X</i>
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 130.00	<i>30sn</i>
TOTAL	\$	1,222.82	
TOTAL PARTS	\$	12,397.00	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>132d</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>120d</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>90d</i>

Trans-cab Auto Services Pte Ltd**AAD2107-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD323C

To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	10d
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	12d/
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2d/

TOTAL \$ 7,580.00**Over All Total \$ 31,151.19****(LUMP SUM)****Repair Days****20 DAYS***8 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: