

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

**India International Insurance Pte Ltd**

64 , Cecil Street # 04 - 05  
 IOB Building  
 Singapore 049711  
 Tel : 6347 - 6100  
 Fax : 6224 - 4174

*Jasper*

**Quotation**

DATE : 02.08.2021  
 VEH NO : SGD1328U  
 MODEL : Toyota Estima  
 D O A : 03.07.2021  
 YR REF : SGY8536D

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SGD1328U (TOYOTA ESTIMA)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Rear Bumper <i>Deformed</i>	1	715.90 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	125.00 X
3	Rear Bumper Reflector - RH <i>new</i>	1	67.10 X
4	Rear Bumper Lower Cover <i>new</i>	1	48.90 X
			<hr/>
			956.90
			<hr/>
			(239.23)
			<hr/>
			\$ 717.68

**S/NET ITEMS**

1	Front Bumper Clips <i>new</i>	230	1 set	30.00 ✓
2	Reverse Sensor <i>Damaged</i>		1	<del>280.00</del> 200
				<hr/>
				310.00

**Total Parts \$ 1,027.68**

**LABOUR CHARGE**

1	To knocking & pull out rear portion & renew above parts		\$	<del>400.00</del> 250
2	To putty & spray up paint works (front)		\$	<del>400.00</del> 250
3	To remove reverse sensor		\$	<del>100.00</del> 50

**Total Labour \$ 900.00**

**Grand Total \$ 1,927.68**

*total: 1316.92*  
*H/S: 1050.*  
*03Days.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary **NOTE** must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: