

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 11 Oct 2021

Preliminary Advice

Insured Vehicle No	: SKS1374J	Accident Date	: 07/07/2021
TP Vehicle No	: SLC2931S	Assignment Date	: 09/07/2021
Make	: HONDA VEZEL	Est. Duration of Repair	: 9
Date of Inspection	: 12/07/2021		
Inspection At	: SIN YU SIN WORKSHOP (HQ) 1 KAKI BUKIT AVE 6 #01-52 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,178.08
Revised Amount	:S\$	10,007.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,007.04
 Lump Sum Repair	 :S\$	 8,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	53,000.00
COE / PARF Rebate	:S\$	30,656.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,344.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.