

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21007507/GQCQ2**Date:** 07/06/2023**REFERENCE**

|                              |                                               |                             |                    |           |                         |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------|-------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNW00117692002 |           |                         |
| <b>Claimant Vehicle No :</b> | SLN2366R                                      | <b>Insured Vehicle No :</b> | GBE5194R           |           |                         |
| Date of Loss:                | 08/07/2021                                    | Nature of Claim:            | TP                 | Claim No: | SNM21D203805/C02/CHEESC |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLN2366R</b>                   | Engine No:  | P520443569        |
| Make & Model:               | MAZDA 3, 1.5 SEDAN AT EU6 (A)     | Chassis No: | JM6BN22A8H0152039 |
| Reg. Date:                  | 26/04/2017 (Man. Year: 2017)      | Odometer:   | 0 km              |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 1496 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 205/60 R16   | Rear Tyre Size:  | 205/60 R16   |
| Front Left Side:  | Firenza 6 mm | Rear Left Side:  | Firenza 6 mm |
| Front Right Side: | Firenza 6 mm | Rear Right Side: | Firenza 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 6,866.80          | 4,374.40          | 2,492.40          | 36.30         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,020.00          | 1,690.00          | 1,330.00          | 44.04         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>9,886.80</b>   | <b>6,064.40</b>   | <b>3,822.40</b>   | <b>38.66</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>4,850.00</b>   |                   |               |
| <b>(S\$)</b>                             | 9,886.80          | 4,850.00          | 5,036.80          | 50.94         |
| <b>+ GST 8.00/8.00% (S\$)</b>            | 790.94            | 388.00            | 402.94            | 50.94         |
| <b>Nett Amount (S\$)</b>                 | <b>10,677.74</b>  | <b>5,238.00</b>   | <b>5,439.74</b>   | <b>50.94</b>  |

**INSPECTION**

|                             |            |               |                                                                                                          |
|-----------------------------|------------|---------------|----------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 09/07/2021 |               |                                                                                                          |
| Date Inspected:             | 12/07/2021 | Inspected At: | Lion City Rental (jalan Lam Huat ) (HQ)<br>60 Jalan Lam Huat, 04-35/36 Carros Centre<br>Singapore 737869 |
| Estimated Period of Repair: | 5.0 days   |               |                                                                                                          |

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 05 Jun 2023)                  |
| Parts:        | 143                                                                                                                                                                          | MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| Print Code:   | (Unsubmitted, no print-code for SLN2366R)                                                                                                                                    |                                                                |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's                                         | Amount            |
|-----|-----|----------|---------------------------------|---------------|----------------------------------------------------|-------------------|
| 1   | 1   |          | *REAR BUMPER                    | Dented        | 1,300.00 FL                                        | *1,029.00 FL      |
| 2   | 2   |          | *REAR BUMPER RETAINER (LH & RH) | Distorted     | 116.30 FL                                          | *116.30 FL        |
| 3   | 1   |          | *REAR BUMPER REINFORCEMENT      | Bent          | 564.20 FL                                          | *499.00 FL        |
| 4   | 1   |          | *REAR BUMPER LOWER COVER        | Not Necessary | 300.00 FL                                          | *- FL             |
| 5   | 1   |          | *REAR BOOT RH REFLECTOR /LAMP   | Cracked       | 478.30 FL                                          | *358.00 FL        |
| 6   | 1   |          | *REAR BOOT LH REFLECTOR /LAMP   | Cracked       | 478.30 FL                                          | *358.00 FL        |
| 7   | 1   |          | *REAR BOOT                      | Buckled       | 1,200.00 FL                                        | *1,067.00 FL      |
| 8   | 1   |          | *REAR BOOT LOCK ASSY            | Bent          | 113.50 FL                                          | *113.50 FL        |
| 9   | 1   |          | *REAR BOOT LOCK CATCH           | Not Necessary | 160.70 FL                                          | *- FL             |
| 10  | 1   |          | *REAR BOOT WEATHERSTRIP         | Torn          | 113.50 FL                                          | *113.50 FL        |
| 11  | 1   |          | *REAR END PANEL                 | Buckled       | 800.00 FL                                          | *530.00 FL        |
| 12  | 1   |          | *REAR END PANEL TOP GARNISH     | Cracked       | 220.00 FL                                          | *220.00 FL        |
| 13  | 1   |          | *REAR SPARE TYRE PANEL          | Not Necessary | 950.00 FL                                          | *- FL             |
| 14  | 1   |          | *R/R TAILLAMP                   | Cracked       | 900.00 FL                                          | *535.00 FL        |
| 15  | 1   |          | *REAR BUMPER LH SIDE BRACKET    | Not Necessary | 80.00 FL                                           | *- FL             |
| 16  | 1   |          | *REAR BUMPER RH SIDE BRACKET    | Not Necessary | 80.00 FL                                           | *- FL             |
| 17  | 1   |          | *REAR BOOT SKYACTIV EMBLEM      | Necessary     | 66.80 FL                                           | *66.80 FL         |
| 18  | 1   |          | *REAR BOOT MAZDA LOGO           | Necessary     | 78.30 FL                                           | *78.30 FL         |
| 19  | 1   |          | *REAR BOOT MAZDA 3 EMBLEM       | Necessary     | 56.10 FL                                           | *56.10 FL         |
| 20  | 1   |          | *REAR BUMPER RH TOW COVER       | Missing       | 40.00 FL                                           | *40.00 FL         |
| 21  | 1   |          | *REVERSE SENSOR                 | Cracked       | 240.00 FS                                          | *200.00 FS        |
| 22  | 1   |          | *REAR BUMPER CLIPS              | Necessary     | 150.00 FS                                          | *30.00 FS         |
|     |     |          |                                 |               | Sub Total (S\$)                                    | 8,486.00 5,410.50 |
|     |     |          |                                 |               | - List Item Discount on L Items 20.00/20.00% (S\$) | 1,619.20 1,036.10 |
|     |     |          |                                 |               | Total Parts (S\$)                                  | 6,866.80 4,374.40 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                                                                                                                                       | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                   |          |                 |                 |
| 1                               | TO LABOUR CHARGE FOR REMOVING REAR BUMPER ,REAR BOOT ,END PANEL AND R/R AND R/L FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS | New      | 1,500.00        | 750.00          |
| 2                               | TO RESPRAY REAR BUMPER ,REAR BOOT ,REAR END PANEL ,SPARE TYRE PANEL ,R/R AND R/L FENDER                                                           | New      | 1,400.00        | 880.00          |
| 3                               | TO REMOVE AND INSTALL REAR FENDER GARNISH AND REAT SEAT UPHOLSTERY OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS                                 | New      | 120.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                   |          | <b>3,020.00</b> | <b>1,690.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >