

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chee So Chow

Date: 26 May 2023

**Preliminary Advice**

Insured Vehicle No : GBE5194R  
TP Vehicle No : SLN2366R  
Make : MAZDA 3  
Date of Inspection : 12/07/2021  
Inspection At : LION CITY RENTAL (JALAN LAM HUAT ) (HQ)  
60 JALAN LAM HUAT, 04-35/36 CARROS CENTRE  
SINGAPORE 737869  
Accident Date : 08/07/2021  
Assignment Date : 09/07/2021  
Est. Duration of Repair : 5

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,886.80
Revised Amount	:S\$	7,140.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,140.24
Lump Sum Repair	:S\$	5,700.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.