

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Date 13/07/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLN2366R

Chassis No: JM6BN22A8H0152039

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT: 08/07/2021

YOUR INSURED VEHICLE NUMBER: GBE5194R

MILEAGE: km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE	
1	Rear bumper ✓	1PC	\$1,300.00	\$1,300.00	- DD 1029.
2	Rear bumper retainer (LH & RH) ✓	2PCS	\$116.30	\$116.30	- DIS
3	Rear bumper reinforcement ✓	1PC	\$564.20	\$564.20	- BT449
4	Rear bumper lower cover X	1PC	\$300.00	\$300.00	- NN
5	Rear boot RH reflector / lamp ✓	1PC	\$478.30	\$478.30	- CRA 358
6	Rear boot LH reflector / lamp ✓	1PC	\$478.30	\$478.30	- CRA 358
7	Rear boot ✓	1PC	\$1,200.00	\$1,200.00	- BUC 1067
8	Rear boot lock assy ✓	1PC	\$113.50	\$113.50	- BT
9	Rear boot lock catch X	1PC	\$160.70	\$160.70	- NN
10	Rear boot weatherstrip ✓	1PC	\$113.50	\$113.50	- TN
11	Rear end panel ✓	1PC	\$800.00	\$800.00	- BUC 530
12	Rear end panel top garnish ✓	1PC	\$220.00	\$220.00	- CRA
13	Rear spare tyre panel X	1PC	\$950.00	\$950.00	- NN
14	R/R taillamp ✓	1PC	\$900.00	\$900.00	- CRA 535
15	Rear bumper LH side bracket X	1PC	\$80.00	\$80.00	- NN
16	Rear bumper RH side bracket X	1PC	\$80.00	\$80.00	- NN
17	Rear boot SKYACTIV emblem ✓	1PC	\$66.80	\$66.80	- NEC
18	Rear boot Mazda logo ✓	1PC	\$78.30	\$78.30	- NEC
19	Rear boot Mazda 3 emblem ✓	1PC	\$56.10	\$56.10	- NEC
20	Rear bumper RH tow cover ✓	1PC	\$40.00	\$40.00	- MIS
	Total		\$8,096.00	\$8,096.00	- 206
	Less 20%		\$1,619.20	\$1,619.20	- 5220.24
	Total		\$6,476.80	\$6,476.80	

S/Nett

1	Reverse sensor ✓		\$240.00	200	- CRA
2	Rear bumper clips ✓		\$150.00	30	- NEC
	Total		\$390.00		- 230

LABOUR CHARGES

- 1 To labour charge for removing rear bumper, rear boot, end panel and R/R and R/L fender out to facilitate repairs and replacement of damaged parts

\$1,500.00 750

- 2 To respray rear bumper, rear boot, rear end panel, spare tyre panel, R/R and R/L fender

\$1,400.00 880

- 3 To remove and install rear fender granish and rear seat upholstery out to facilitate replacement of damaged parts

\$120.00 60

Grand Total

LABOUR TOTAL S\$: \$3,020.00
TOTAL S\$: \$3,410.00
\$9,886.80
7% GST \$238.70
GRAND TOTAL S\$: \$13,535.50

1690

5 Days

7140.24
- 10%
5712.17
4100.00
4850