

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile					
	EQ INSURANCE C	OMPANY LTD	Ref:	CS3/EQI21007508/Evf3	
	5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date:	09/07/2021	
			Code	EQI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLZ 9633K	Veh. Inspected	SMQ 8648K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	DM21HO00971-JG	Excess (\$)	0.00	
	Assign From	JOEL GOH	Assign Date	09/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
5.	General Information				
	Accident Date	06/07/2021	Inspection Date	12/07/2021	
	Survey held at	MTM PERFORMANCE AUTO PTE. LTD.			
		48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB SINGAPORE 608586			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				