

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007518/AGA3Q2**Date:** 20/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800089458
Claimant Vehicle No :	SGS6592K	Insured Vehicle No :	SBV4188B
Date of Loss:	23/06/2021	Nature of Claim:	TP
		Claim No:	8232674333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS6592K	Engine No:	1NZX522348
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY4204218585
Reg. Date:	21/03/2007 (Man. Year: 2006)	Odometer:	438965 km
Colour:	Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,481.22	636.45	3,844.77	85.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	780.00	2,970.00	79.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,231.22	1,416.45	6,814.77	82.79
Approved Total (Overridden) (\$\$)		1,100.00		
Nett Amount (\$\$)	8,231.22	1,100.00	7,131.22	86.64
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,407.45		

INSPECTION

Date of Assignment:	07/07/2021	
Date Inspected:	07/07/2021	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Not Necessary	556.10 FL	*- FL
2	1		*BOOT LID BADGE	Not Necessary	56.00 FL	*- FL
3	1		*BOOT LID EMBLEM VIOS	Not Necessary	48.00 FL	*- FL
4	1		*BOOT LID EMBLEM VVTI	Not Necessary	48.00 FL	*- FL
5	1		*BOOT LID EMBLEM 1.5	Not Necessary	46.00 FL	*- FL
6	1		*BOOT LID EMBLEM E	Not Necessary	42.00 FL	*- FL
7	1		*BOOT LID INNER LOCK	Not Necessary	98.20 FL	*- FL
8	1		*BOOT LID LOCK CATCH	Not Necessary	36.60 FL	*- FL
9	1		*BOOT LID WEATHERSTRIP	Not Necessary	193.40 FL	*- FL
10	1		*REAR BUMPER	Deformed	475.60 FL	*475.60 FL
11	1		*REAR BUMPER SIDE RETAINERS	N/S Damaged	161.40 FL	*38.00 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
13	1		*TAILLAMPS	N/S Cracked	792.80 FL	*295.00 FL
14	2		*TAILLAMPS INNER SEALER	Not Necessary	60.00 FL	*- FL
15	2		*SET TAILLAMPS CLIPS	Necessary	50.00 FL	*10.00 FL
16	1		*END PANEL	Repair	666.10 FL	*- FL
17	1		*END PANEL TOP TRIM	Not Necessary	232.70 FL	*- FL
18	1		*SET END PANEL TOP TRIM CLIPS	Not Necessary	30.00 FL	*- FL
19	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	159.60 FL	*- FL
20	1		*SPARE TYRE PANEL	Not Necessary	523.20 FL	*- FL
21	2		*REAR FENDER INNER TRIMS	Not Necessary	532.20 FL	*- FL
22	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FL	*- FL
23	2		*REAR FENDER INNER COWLING	Not Necessary	290.40 FL	*- FL
24	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
26	1		*SET BODY PANEL JOINT SEALANT	Not Necessary	120.00 FS	*- FS
27	1		*REAR EXHAUST CHROME PIPE	Not Necessary	140.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,788.30	848.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,307.08	212.15
Total Parts (\$\$)	4,481.22	636.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	300.00
2	SPRAY PAINTING	New	1,600.00	400.00
3	CHECK WIRING ON TAILLAMPS	New	120.00	30.00
4	ANTI RUST	New	100.00	0.00
5	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	0.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	50.00
7	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	0.00
Gross Labour Cost (\$\$)			3,750.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >