

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0561/2021/GW
DATE : 07-Jul-21
WIP : 34389

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY 9/7/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

7 days - ok - Jy - 8 Sep 21

OWNER'S NAME : MR RANJEEV KUMAR NANTA KUMAR
ADDRESS : BLK 677 A YISHUN RING ROAD
#06-1992
SINGAPORE 701677
TELEPHONE : HP +65 84187605
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800058563-02
VEHICLE NO : **SMA 377 D**
MODEL CODE : A3 SEDAN 1.0 TFSI S TRONIC
MODEL YEAR : 25/05/2018
ENGINE NO : CHZ 443895
CHASSIS NO : WAUZZZ8V01059995
MILEAGE :
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 05-Jul-21
PLACE OF ACCIDENT : BLK 646 YISHUN STREET 61

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 377 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	S/N \$	280.00	
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$ 560.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS FRONT FENDER AND LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,500.00	\$ 1,100.00
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE, LHS SILL PANEL AND LHS FRONT FENDER.	\$	5,500.00	\$ 2,750.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	10,172.00	\$ 4,602.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 377 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR LH	1	\$ 3,039.00	\$ 2,431.20
2	FRONT DOOR OUTER SEAL LH	1	\$ 161.00	\$ 128.40
3	BONDING AGENT	1	\$ 49.00	
4	CLEANING SOLUTION	1	\$ 68.00	
5	APPLICATOR	1	\$ 8.00	
6	FRONT DOOR ATTACHMENT PARTS LH	1	\$ 241.00	
7	FRONT DOOR CATCH LH	1	\$ 105.00	
8	FRONT EXTERIOR MOUNTING LH	1	\$ 1,012.00	
9	FRONT WING MIRROR CAP LH	1	\$ 169.00	
10	REAR DOOR LH	1	\$ 3,019.00	\$ 2,431.20
11	REAR DOOR OUTER SEAL LH	1	\$ 161.00	\$ 128.40
12	BONDING AGENT	1	\$ 49.00	
13	CLEANING SOLUTION	1	\$ 68.00	
14	APPLICATOR	1	\$ 8.00	
15	REAR DOOR ATTACHMENT PARTS LH	1	\$ 129.00	
16	REAR DOOR CATCH LH	1	\$ 94.00	\$ 74.80
17	SUNDRIES		\$ 350.00	\$ 26.16
TOTAL SPARE PARTS		:	\$ 8,730.00	\$ 5,220.16
TOTAL LABOUR CHARGES		:	\$ 10,172.00	\$ 4,602.00
GRAND TOTAL		:	\$ 18,902.00	\$ 9,822.16

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-13/08/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT