

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

*TP China.
Xiao Chen.*

ALOY & JEM SERVICES
 BLK 208 PASRI RIS STREET 21 #10-344
 SINGAPORE 510208

Contact : 98391887

ESTIMATE

Repair Code : CLM16872

Date in : 09/07/2021

Vehicle Num. : GBJ4005J

Model : TOYOTA HIACE 2.8 DX DIESEL TURBO AT 2WD

Chassis/Eng# : GDH2012004698/1GD8375646

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
* REAR BUMPER <i>Noe Nec</i>	1	430.90	430.90
REAR RH TAILLAMP <i>wt</i>	1	354.80	✓ 354.80
REAR RH TAILLAMP LOWER GARNISH <i>xt m</i>	1	157.00	157.00
REAR TAILGATE <i>Dented</i>	1	2162.70	✓ 2,162.70
REAR TAILGATE 'LOGO' EMBLEM <i>3 new</i>	1	71.60	✓ 71.60
REAR TAILGATE HIACE STICKER EMBLEM	1	58.00	✓ 58.00
REAR TAILGATE INNER TRIM BOARD COVER <i>2 new</i>	1	181.00	181.00
REAR TAILGATE LOWER CLUST SEAL COVER L/R <i>2 new</i>	2	11.70	23.40
REAR TAILGATE LOWER JOINT SEAL COVER L/R <i>2 new</i>	2	11.60	23.20
REAR TAILGATE OUTER GARNISH <i>wt</i>	1	261.60	✓ 261.60
REAR TAILGATE WINDSCREEN GLASS <i>shattered</i>	1	1340.00	✓ 1,340.00
Subtotal before discount			5,064.20
Percentage discount 25%			1,266.05
Sub-total 1			3,798.15
REAR BUMPER CLIPS - SET <i>2 new</i>	1	50.00	50.00
REAR RH TAILLAMP CLIPS - SET <i>new</i>	1	30.00	30.00
REAR TAILGATE '1200KG' STICKER <i>3 new</i>	1	50.00	50.00
REAR TAILGATE '6PAX' STICKER <i>3 new</i>	1	25.00	25.00

*4248.20
3186.52*

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ALOY & JEM SERVICES
 BLK 208 PASRI RIS STREET 21 #10-344
 SINGAPORE 510208

Contact : 98391887

ESTIMATE

Repair Code : CLM16872
 Date in : 09/07/2021
 Vehicle Num. : GBJ4005J
 Model : TOYOTA HIACE 2.8 DX DIESEL TURBO AT 2WD
 Chassis/Eng# : GDH2012004698/1GD8375646

REAR TAILGATE '70KM/H' STICKER <i>NEC</i>	1	25.00	<i>15</i>	25.00
REAR TAILGATE INNER TRIM BOARD COVER CLIPS - SET <i>NEC</i>	1	50.00	<i>X</i>	50.00
REAR TAILGATE WINDSCREEN GLASS INNER SEAL <i>NEC</i>	1	80.00	<i>40</i>	80.00
REAR TAILGATE WINDSCREEN GLASS SEALANT	1	80.00	<i>60</i>	80.00
REAR TAILGATE WINDSCREEN GLASS SOLAR FILM <i>NEC</i>	1	450.00	<i>280</i>	450.00
Subtotal before discount				840.00
Percentage discount 0%				0.00
Sub-total 2				840.00
Parts-total				4,638.15

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To send vehicle for cleaning, shampoo, upholstery and cushion seat.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove n refix rear gate mechanism and check for function

Labour Total 1,960.00
Parts & Labour Total 6,598.15

1240
670
30 60.00
120 150.00
X 100.00
80 120.00
500 700.00
400 700.00
30 50.00
60 80.00

total: 4876.52
n/s: 3.9K.

3.9K.

*** This is a computer-generated document which requires no signature.***