

ASS. REC. BY:

REF:

A16 / 210075351Kp

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

1. B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMX 8579P

Yr Regn:

02, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pinter

c.c

1496

Colour

M. Marom

A/C:

Insured / Std / NI / NA

Sp. Reading

20802

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

N14P170. 7179638

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / R / m / STD A / R / m or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

9/7/21

D.O.I.

13/7/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Firm's

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



# DING AUTO PTE LTD

Blk 176 #04-06

Sin Ming Drive (Sin Ming Autocare)

Singapore 575721

Tel: 83636141

Fax: 6452 0614

Vehicle:	SMX8579P
Model:	TOYOTA SIENTA HYBRID 1.5X CVT
Chassis:	NHP1707179638

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYOR MARKING
1	REAR BOOTLID	1	\$ 1,131.90	25%	\$ 848.92	✓
2	REAR BOOTLID GARNISH	1	\$ 207.90	25%	\$ 155.92	✓
3	REAR BOOTLID DAMPER ABSORBER RHS	1	\$ 242.50	25%	\$ 181.87	X
4	REAR BOOTLID DAMPER ABSORBER LHS	1	\$ 242.50	25%	\$ 181.87	X
5	REAR BOOTLID INSULATOR	1	\$ 138.00	25%	\$ 103.50	X
6	REAR BOOTLID LOCK ASSY CPL	1	\$ 467.60	25%	\$ 350.70	✓
7	REAR BOOTLID RUBBER SEAL	1	\$ 372.30	25%	\$ 279.22	✓
8	REAR OUTER TAIL LAMP RHS	1	\$ 358.80	25%	\$ 269.10	X
9	REAR OUTER TAIL LAMP LHS	1	\$ 358.80	25%	\$ 269.10	X
10	REAR INNER LAMP RHS	1	\$ 190.90	25%	\$ 143.17	X
11	REAR INNER LAMP LHS	1	\$ 190.90	25%	\$ 143.17	X
12	REAR BOOTLID BADGE	1	\$ 67.50	25%	\$ 50.62	✓
13	REAR BUMPER	1	\$ 408.70	25%	\$ 306.52	✓
14	REAR BUMPER UPPER GARNISH	1	\$ 190.00	25%	\$ 142.50	✓
15	REAR BUMPER SUPPORT PANEL	1	\$ 433.60	25%	\$ 325.20	✓
16	REAR BUMPER GARNISH (R/L/CTR X 3PCS)	1	\$ 449.40	25%	\$ 337.05	X
17	REAR BUMPER REFLECTOR RHS	1	\$ 191.00	25%	\$ 143.25	X
18	REAR BUMPER REFLECTOR LHS	1	\$ 191.00	25%	\$ 143.25	✓
19	REAR BUMPER TOWING CAP	1	\$ 23.00	25%	\$ 17.25	X
20	REAR BUMPER RETAINER RHS	1	\$ 75.50	25%	\$ 56.62	X
21	REAR BUMPER RETAINER LHS	1	\$ 75.50	25%	\$ 56.62	X
22	REAR END INNER PANEL	1	\$ 696.30	25%	\$ 522.22	✓
23	REAR WIPER LINKAGE	1	\$ 94.00	25%	\$ 70.50	X
24	REAR WIPER MOTOR	1	\$ 675.70	25%	\$ 506.77	X
25	REAR WIPER ARM	1	\$ 42.60	25%	\$ 31.95	X
26	REAR BUMPER HARDNESS WIRE CPL	1	\$ 476.70	25%	\$ 357.52	X
27	REAR BOOTLID SENSOR (END-PANEL)	1	\$ 107.00	25%	\$ 80.25	✓
28	REAR EXHAUST TAIL PIPE (END)	1	\$ 805.40	25%	\$ 604.05	X
29	REAR BOOTLID INNER SHIELD	1	\$ 77.70	25%	\$ 58.27	✓
30	BATTERY COVER	1	\$ 185.50	25%	\$ 139.12	✓
31	BATTERY GARNISH	1	\$ 293.50	25%	\$ 220.12	✓
32	BATTERY BRACKET CPL	1	\$ 85.30	25%	\$ 63.97	X
33	BATTERY TRAY	1	\$ 52.80	25%	\$ 39.60	X
34	REAR WINDSCREEN	1	\$ 1,181.70	25%	\$ 886.27	✓
35	REAR WINDSCREEN MOULDING	1	\$ 180.50	25%	\$ 135.37	✓
TOTAL:					\$ 8,221.40	

Not Withheld  
Resurvey B4paim  
6 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

SPECIAL NETT		QTY	PRICE	SURVEYOR MARKING
1	REAR BUMPER AND AUDIO GUARD CLIP/BRAKET	1	\$ 100.00	X
2	REAR REVERSE CAMERA ASSY	1	\$ 300.00	X
3	REAR REVERSE SENSOR ASSY	1	\$ 330.00	7
4	REAR WINDSCREEN TINTED	1	\$ 300.00	X
5	WINDSCREEN PRIMER AND SEALANT	1	\$ 80.00	801
6	NUMBER PLATE	1	\$ 40.00	X
			\$ 1,170.00	

LABOUR		PRICE	SURVEYOR MARKING
1	PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	\$ 1,000.00	601
2	STRAIGHTEN AND ALIGN REAR BOOT PLATFORM/REAR CHASSIS	\$ 550.00	7
3	SPRAY PAINT - REAR BUMPER, FENDER LHS, END-PANEL, SPARE TYRE BOOTH, BOOTLID(OUTER & INNER)	\$ 1,500.00	601
4	REMOVE AND REFIT REAR BUMPER, REAR BOOTLID COMPONENTS	\$ 150.00	601
5	REMOVE AND REFIT REAR WINDSCREEN	\$ 150.00	1201
6	REMOVE AND REPAIR EXHAUST SYSTEM	\$ 180.00	X
7	ALIGN AND TEST REVERSE CAMERA, REVERSE SENSOR AND BOOTLID SENSOR WIRING	\$ 150.00	601
8	ALIGN AND TEST TAIL LAMP WIRING	\$ 50.00	201
TOTAL:		\$ 3,730.00	

PARTS	\$ 8,221.40	
LABOUR	\$ 3,730.00	
SPECIAL NETT	\$ 1,170.00	
TOTAL	\$ 13,121.40	
GST 7%	\$ 918.50	
FINAL TOTAL	\$ 14,039.90	



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	12/07/2021 10:01 (SGT)
Date of Accident	09/07/2021 21:25 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	ALONG CTE EXPRESSWAY TOWARDS SLE
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX8579P
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	ATOLL DISCOVERY PTE LTD
Company Reg No	2XXXXX064W
Email Address	derrick@25l.com.sg
Mobile Phone No	(Phone) +65-88112211
Alternative Phone No	+65-88112211

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Sienta
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5120851279
Cover Note Number	-

### DRIVER

Name of Driver	LAI JIA WEI SHINA
NRIC No	SXXXX327D

Accident report SS17217C0001

Page 1 of 22

15/11/1983	
Outdoor	
19/03/2009	
12 YEARS AND 4 MONTHS	
Female	
(Phone) +65-90666042	
-	
shina_ko83@yahoo.com.sg	
BLK 279 C	
#14-535	
543279	
No	
Hirer	
No	
-	
-	

Cond GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

See OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	6
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	unknown
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH DRIVER
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2854D
-----------------------------	----------