

DING AUTO PTE LTD

Blk 176 #04-06

Sin Ming Drive (Sin Ming Autocare)

Singapore 575721

Tel: 83636141

Fax: 6452 0614

Vehicle:	SMX8579P
Model:	TOYOTA SIENTA HYBRID 1.5X CVT
Chassis:	NHP1707179638

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYOR MARKING
1	REAR BOOTLID	1	\$ 1,131.90	25%	\$ 848.92	✓
2	REAR BOOTLID GARNISH	1	\$ 207.90	25%	\$ 155.92	✓
3	REAR BOOTLID DAMPER ABSORBER RHS	1	\$ 242.50	25%	\$ 181.87	X
4	REAR BOOTLID DAMPER ABSORBER LHS	1	\$ 242.50	25%	\$ 181.87	X
5	REAR BOOTLID INSULATOR	1	\$ 138.00	25%	\$ 103.50	X
6	REAR BOOTLID LOCK ASSY CPL	1	\$ 467.60	25%	\$ 350.70	✓
7	REAR BOOTLID RUBBER SEAL	1	\$ 372.30	25%	\$ 279.22	✓
8	REAR OUTER TAIL LAMP RHS	1	\$ 358.80	25%	\$ 269.10	X
9	REAR OUTER TAIL LAMP LHS	1	\$ 358.80	25%	\$ 269.10	X
10	REAR INNER LAMP RHS	1	\$ 190.90	25%	\$ 143.17	X
11	REAR INNER LAMP LHS	1	\$ 190.90	25%	\$ 143.17	X
12	REAR BOOTLID BADGE	1	\$ 67.50	25%	\$ 50.62	✓
13	REAR BUMPER	1	\$ 408.70	25%	\$ 306.52	✓
14	REAR BUMPER UPPER GARNISH	1	\$ 190.00	25%	\$ 142.50	✓
15	REAR BUMPER SUPPORT PANEL	1	\$ 433.60	25%	\$ 325.20	✓
16	REAR BUMPER GARNISH (R/L/CTR X 3PCS)	1	\$ 449.40	25%	\$ 337.05	X
17	REAR BUMPER REFLECTOR RHS	1	\$ 191.00	25%	\$ 143.25	X
18	REAR BUMPER REFLECTOR LHS	1	\$ 191.00	25%	\$ 143.25	X
19	REAR BUMPER TOWING CAP	1	\$ 23.00	25%	\$ 17.25	X
20	REAR BUMPER RETAINER RHS	1	\$ 75.50	25%	\$ 56.62	X
21	REAR BUMPER RETAINER LHS	1	\$ 75.50	25%	\$ 56.62	X
22	REAR END INNER PANEL	1	\$ 696.30	25%	\$ 522.22	✓
23	REAR WIPER LINKAGE	1	\$ 94.00	25%	\$ 70.50	X
24	REAR WIPER MOTOR	1	\$ 675.70	25%	\$ 506.77	X
25	REAR WIPER ARM	1	\$ 42.60	25%	\$ 31.95	X
26	REAR BUMPER HARDNESS WIRE CPL	1	\$ 476.70	25%	\$ 357.52	X
27	REAR BOOTLID SENSOR (END-PANEL)	1	\$ 107.00	25%	\$ 80.25	✓
28	REAR EXHAUST TAIL PIPE (END)	1	\$ 805.40	25%	\$ 604.05	X
29	REAR BOOTLID INNER SHIELD	1	\$ 77.70	25%	\$ 58.27	✓
30	BATTERY COVER	1	\$ 185.50	25%	\$ 139.12	✓
31	BATTERY GARNISH	1	\$ 293.50	25%	\$ 220.12	✓
32	BATTERY BRACKET CPL	1	\$ 85.30	25%	\$ 63.97	X
33	BATTERY TRAY	1	\$ 52.80	25%	\$ 39.60	X
34	REAR WINDSCREEN	1	\$ 1,181.70	25%	\$ 886.27	✓
35	REAR WINDSCREEN MOULDING	1	\$ 180.50	25%	\$ 135.37	✓
TOTAL:					\$ 8,221.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NOT Notified
Resurvey Begain

6 day

11/11/21 8 4150/p

Res 16/11/21
10:30am

Note: 1) Lower sump repair

2) Surveyor request PRS

3) Inform surveyor, Kenneth.

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	REAR BUMPER AND MUD GUARD CLIP/BACKET	1	\$ 100.00	X
2	REAR REVERSE CAMERA ASSY	1	\$ 300.00	X
3	REAR REVERSE SENSOR ASSY	1	\$ 350.00	200/n
4	REAR WINDSCREEN TINTED	1	\$ 300.00	X
5	WINDSCREEN PRIMER AND SEALANT	1	\$ 80.00	80/n
6	NUMBER PLATE	1	\$ 40.00	X
			\$ 1,170.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	\$ 1,000.00	
2	STRAIGHTEN AND ALIGN REAR BOOT PLATFORM/REAR CHASSIS	550.00	X
3	SPRAY PAINT - REAR BUMPER, FENDER LHS, END-PANEL, SPARE TYRE BOOTH, BOOTLID(OUTER & INNER)	\$ 1,500.00	
4	REMOVE AND REFIT REAR BUMPER, REAR BOOTLID COMPONENTS	\$ 150.00	80/n
5	REMOVE AND REFIT REAR WINDSCREEN	\$ 150.00	120/n
6	REMOVE AND REPAIR EXHAUST SYSTEM	\$ 180.00	X
7	ALIGN AND TEST REVERSE CAMERA, REVERSE SENSOR AND BOOTLID SENSOR WIRING	\$ 150.00	80/n
8	ALIGN AND TEST TAIL LAMP WIRING	\$ 50.00	20/n
	TOTAL:	\$ 3,730.00	

PARTS	\$ 8,221.40	
LABOUR	\$ 3,730.00	
SPECIAL NETT	\$ 1,170.00	
TOTAL	\$ 13,121.40	
GST 7%	\$ 918.50	
FINAL TOTAL	\$ 14,039.90	

850/n
800/n