



Your Ref : CMTD2101899/SYH

Date: 30th July 2021

Our Ref : CS/SMO21007537/Aqf3e2

M/s Sampo Insurance Singapore PL

50 Raffles Place #03-03

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLQ 2796S
INSURED VEHICLE: SLE 7555B
ACCIDENT ON 24/06/2021**

Instruction was received to inspect the vehicle Reg. No. SLQ 2796S. The inspection was conducted on 24/06/2021 at the premises of M/s SK Automobile Ptd Ltd, 23 Kaki Bukit Ave 4 #03-01, Singapore 415933.

The following vehicle information was recorded:

Registration Number	: SLQ 2796S
Make/Model	: Honda Stream 1.8 A
Year of Registration	: 2007
Body Colour	: White
Chassis Number	: RN61037167
Engine Capacity	: 1799 cc

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 9,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 5,289.00)
Nett Liability	<u>S\$ 3,711.00</u> =====

Vehicle Inspected By:



ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.