

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007542/KGS3Q2
Date: 18/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480996
Claimant Vehicle No :	SKZ6020K	Insured Vehicle No :	GBF2956Z
Date of Loss:	10/07/2021	Nature of Claim:	TP
		Claim No:	8099231249SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ6020K	Engine No:	HR16983913B
Make & Model:	NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)	Chassis No:	MNTBBAB17Z0026704
Reg. Date:	28/01/2016 (Man. Year: 2015)	Odometer:	42893 km
Colour:	Metallic Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,055.43	2,930.63	2,124.80	42.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,280.00	330.00	20.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,665.43	4,210.63	2,454.80	36.83
Approved Total (Overridden) (S\$)		3,350.00		

	(S\$)	6,665.43	3,350.00	3,315.43	49.74
+ GST 7.00/7.00% (S\$)		466.58	234.50	232.08	49.74
Nett Amount (S\$)		7,132.01	3,584.50	3,547.51	49.74
+ Loss of Use (5.0 x S\$60.00/day) (S\$)			300.00		
+ Doc/Search Fee (S\$)			7.45		
Nett Liability (S\$)			3,891.95		

INSPECTION

Date of Assignment: 12/07/2021

Date Inspected: 13/07/2021

Inspected At:

Lim Tan Motor Pte Ltd (HQ)
Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	686.20 FN	*607.00 FN
2	1		*REAR BUMPER SPONGE CENTRE	Serviceable	49.60 FN	*- FN
3	2		*REAR BUMPER SPONGE SIDE	Serviceable	290.60 FN	*- FN
4	2		*REAR BUMPER SENSOR	Dented	537.12 FS	*200.00 FS
5	2		*REAR BUMPER RETAINER	Distorted	102.40 FN	*102.40 FN
6	10		*REAR BUMPER CLIPS	Necessary	26.00 FN	*26.00 FN
7	1		*REAR END PANEL	Bent	454.30 FN	*454.30 FN
8	1		*REAR END PANEL GARNISH	Dented	185.00 FN	*185.00 FN
9	1		*REAR BOOT LID	Bent	1,244.80 FN	*980.15 FN
10	1		*REAR BOOT RUBBER (50%)	Distorted / Dented	89.82 FS	*49.90 FS
11	1		*REAR BOOT LOCK	Serviceable	135.70 FN	*- FN
12	2		*REAR BOOT LAMPS	Serviceable	326.60 FN	*- FN
13	1		*REAR BOOT OUTER CHROME	Warped	189.90 FN	*189.90 FN
14	1		*REAR BOOT LOWER CHROME	Dented	155.10 FN	*155.10 FN
15	1		*REAR BOOT EMBLEM	Necessary	79.90 FN	*79.90 FN
16	1		*REAR BOOT SYLPHY EMBLEM	Necessary	94.70 FN	*94.70 FN
17	1		*O/S REAR BOOT EMBLEM	Necessary	59.70 FN	*59.70 FN
18	2		*TAIL LAMPS	Serviceable	795.60 FN	*- FN
19	1		*REAR NUMBER PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	5,543.04	3,224.05
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	487.61	293.42
Total Parts (\$\$)	5,055.43	2,930.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT	New	800.00	600.00
2	TO ANTI RUST	New	80.00	60.00
3	TO CHECK REAR WIRING & WATER LEAKAGE	New	30.00	20.00
4	LABOUR CHARGES	New	700.00	600.00
			Gross Labour Cost (\$\$)	1,610.00
				1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >