



ESTIMATE TO REPAIR

VEHICLE NO. : SKZ 6020 K
 MAKE : NISSAN
 MODEL : SYLPHY 1.6 CVT
 YEAR : 2015
 CHASSIS NO : MNTBBAB17Z0026704

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 12.07.2021
 DATE OF ACCIDENT : 10.07.2021
 THIRD PARTY REF : GBF 2956 Z/AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1PC	REAR BUMPER				\$ 686.20
1PC	REAR BUMPER SPONGE CENTRE				\$ 49.60
2PCS	REAR BUMPER SPONGE SIDE		\$ 145.30		\$ 290.60
2PCS	REAR BUMPER SENSOR		\$ 298.40		\$ 596.80
2PCS	REAR BUMPER RETAINER		\$ 51.20		\$ 102.40
10PCS	REAR BUMPER CLIPS		\$ 2.60		\$ 26.00
1PC	REAR END PANEL				\$ 454.30
1PC	REAR END PANEL GARNISH				\$ 185.00
1PC	REAR BOOT LID				\$ 1,244.80
1PC	REAR BOOT RUBBER				\$ 99.80
1PC	REAR BOOT LOCK				\$ 135.70
2PCS	REAR BOOT LAMPS		\$ 163.30		\$ 326.60
1PC	REAR BOOT OUTER CHROME				\$ 189.90
1PC	REAR BOOT LOWER CHROME				\$ 155.10
1PC	REAR BOOT EMBLEM				\$ 79.90
1PC	REAR BOOT SYLPHY EMBLEM				\$ 94.70
1PC	O/S REAR BOOT EMBLEM				\$ 59.70
2PCS	TAIL LAMPS		\$ 397.80		\$ 795.60
	LESS 10%				\$ 5,572.70
					\$ 5,015.43
	REAR NUMBER PLATE	S/N			\$ 40.00
	TO PUTTY & SPRAY PAINT				\$ 800.00
	TO ANTI RUST				\$ 80.00
	TO CHECK REAR WIRING & WATER LEAKAGE				\$ 30.00
	LABOUR CHARGES				\$ 700.00
TG/TL	TOTAL				\$ 6,665.43

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

consent of