

NOT Authorized  
 11 Day &  
 Heavy After Paint  
 5 days



**ESTIMATE TO REPAIR**

VEHICLE NO. : SKZ 6020 K  
 MAKE : NISSAN  
 MODEL : SYLPHY 1.6 CVT  
 YEAR : 2015  
 CHASSIS NO : MNTBBAB17Z0026704

SURVEYOR NAME : Kenneth  
 DATE OF SURVEY : 13-07-21  
 TIME OF SURVEY :

DATE : 12.07.2021  
 DATE OF ACCIDENT : 10.07.2021  
 THIRD PARTY REF : GBF 2956 Z/AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1PC	REAR BUMPER			Net	\$686.20 NETT ✓
1PC	REAR BUMPER SPONGE CENTRE				\$49.60 NETT ✓
2PCS	REAR BUMPER SPONGE SIDE		\$ 145.30		\$290.60 NETT ✓
2PCS	REAR BUMPER SENSOR		\$ 298.40	Net	\$596.80 NETT ✓
2PCS	REAR BUMPER RETAINER		\$ 51.20	Net	\$102.40 NETT ✓
10PCS	REAR BUMPER CLIPS		\$ 2.60	Net	\$26.00 NETT ✓
1PC	REAR END PANEL			Net	\$454.30 NETT ✓
1PC	REAR END PANEL GARNISH			Net	\$185.00 NETT ✓
1PC	REAR BOOT LID			Net	\$1244.80 NETT ✓
1PC	REAR BOOT RUBBER			Net	\$99.80 NETT ✓
1PC	REAR BOOT LOCK			Net	\$135.70 NETT ✓
2PCS	REAR BOOT LAMPS		\$ 163.30	Net	\$326.60 NETT ✓
1PC	REAR BOOT OUTER CHROME			Net	\$189.90 NETT ✓
1PC	REAR BOOT LOWER CHROME			Net	\$155.10 NETT ✓
1PC	REAR BOOT EMBLEM			Net	\$79.90 NETT ✓
1PC	REAR BOOT SYLPHY EMBLEM			Net	\$94.70 NETT ✓
1PC	O/S REAR BOOT EMBLEM			Net	\$59.70 NETT ✓
2PCS	TAIL LAMPS		\$397.80	Net	\$795.60 NETT ✓
	LESS 10%				\$ 5,572.70
					\$ 557.27
					\$ 5,015.43
	REAR NUMBER PLATE	S/N		Net	\$ 40.00 ✓
	TO PUTTY & SPRAY PAINT				\$ 800.00 ✓
	TO ANTI RUST				\$ 80.00 ?
	TO CHECK REAR WIRING & WATER LEAKAGE				\$ 30.00 ✓
	LABOUR CHARGES				\$ 700.00 ?
TG/TL	<b>TOTAL</b>				<b>\$ 6,665.43</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Lim Tan Motor Pte Ltd  
 Blk 178 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website: www.LTM.sg  
 Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd