

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1623 E

1 pc	Tailgate	\$	2,480.40 <i>pl</i>
1 pc	Tailgate lock	\$	24.80 <i>?</i>
1 pc	Emblem "Hyundai"	\$	28.00 <i>ur</i>
1 pc	Emblem "Hybrid"	\$	24.30 <i>ur</i>
1 pc	Emblem "Ioniq"	\$	31.30 <i>ur</i>
1 pc	Antenna Assy- Smart Key	\$	41.90 <i>?</i>
1 pc	Lamp Assy- Rear fog	\$	201.50 <i>?</i>
1 pc	Rear bumper	\$	459.40 <i>dy</i>
1 pc	Rear bumper reinforcement	\$	294.80 <i>ur</i>
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket	\$	20.00 <i>?</i>
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00 <i>?</i>
2 pcs	Rear bumper n/s & o/s stay	\$	276.20 <i>?</i>
2 pcs	Rear bumper n/s & o/s side bracket	\$	66.20 <i>?</i>
1 pc	Rear bumper lower moulding centre	\$	216.50 <i>de</i>
1 pc	Rear bumper lower cover	\$	47.50 <i>?</i>
1 pc	Rear bumper cap hook	\$	9.10 <i>al</i>
2 pcs	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80 <i>X</i>
		\$	4,300.70
		Less 20%	\$ 860.14
			<u>\$ 3,440.56</u>

S/Nett

1 set	Rear bumper clips	\$	48.00 <i>3 ur</i>
1 set	Reverse sensor	\$	280.00 <i>X</i>
1 pc	Rear number plate with casing	\$	50.00 <i>ur - 85</i>
1 set	Tailgate stickers	\$	100.00 <i>80 ur</i>
1 set	End panel inner garnish clips	\$	38.00 <i>X</i>
1 set	Sealant	\$	50.00 <i>4 ur</i>

12-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1623 E

Sundry	\$ 50.00	α
To check wiring	\$ 50.00	30.
To dismantle and refit rear windscreen glass onto new tailgate	\$ 120.00	✓
To dismantle/refit rear tailgate window glass onto new tailgate	\$ 120.00	60.
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00	30.
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	60.
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc <i>* photo-end panel.</i>	\$ 1,000.00	600
To putty and spray painting on rear bumper, end panel, rear bumper lower cover (Black), tailgate	\$ 800.00	700.
To apply rustproofing on the repaired and replaced panels.	\$ 120.00	30
	<u>\$ 6,566.56</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taufik 97495719
WP' 12/7/21 5pm
the Resurvey
p/p Resurvey before paint
04 days
taufik @ khantown.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer

Signature:

Date: