

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

12-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1623 E

1 pc	Tailgate	\$	2,480.40	fl
1 pc	Tailgate lock	\$	24.80	Xun.
1 pc	Emblem "Hyundai"	\$	28.00	ue
1 pc	Emblem "Hybrid"	\$	24.30	ue
1 pc	Emblem "Ioniq"	\$	31.30	ue
1 pc	Antenna Assy- Smart Key	\$	41.90	Xun,
1 pc	Lamp Assy- Rear fog	\$	201.50	?ua
1 pc	Rear bumper	\$	459.40	df
1 pc	Rear bumper reinforcement	\$	294.80	as
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket	\$	20.00	?bt
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00	?bt
2 pcs	Rear bumper n/s & o/s stay	\$	276.20	?bt XNN
2 pcs	Rear bumper n/s & o/s side bracket	\$	66.20	?Xun.
1 pc	Rear bumper lower moulding centre	\$	216.50	de
1 pc	Rear bumper lower cover	\$	47.50	Xun
1 pc	Rear bumper cap hook	\$	9.10	ab
2 pcs	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80	Xun.
		\$	4,300.70	3780.30
		\$	860.14	
		\$	3,440.56	3024.24

Less 20%

S/Nett

1 set	Rear bumper clips	\$	48.00	3ue
1 set	Reverse sensor	\$	280.00	Xun
1 pc	Rear number plate with casing	\$	50.00	an - 85
1 set	Tailgate stickers	\$	100.00	Bove
1 set	End panel inner garnish clips	\$	38.00	X
1 set	Sealant	\$	50.00	4ue

195

12-Jul-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1623 E

Sundry	\$	50.00	OK
To check wiring	\$	50.00	30.
To dismantle and refit rear windscreen glass onto new tailgate	\$	120.00	✓
To dismantle/refit rear tailgate window glass onto new tailgate	\$	120.00	60.
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30.
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	60.
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc <i>* photo-end panel.</i>	\$	1,000.00	600
To putty and spray painting on rear bumper, end panel, rear bumper lower cover (Black), tailgate	\$	800.00	700.
To apply rustproofing on the repaired and replaced panels.	\$	120.00	30
	\$	6,566.56	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

3024.24

195

1630

4849.24

4849.24, 4 days *

Tanpin 97495719

wp' 12/7/21 5pm

the Resurvey

p/p Resurvey before paint

04 days

Tanpin @ Khantaw.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer

Signature:

Date: