

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SLJ 7029 C**
 Model : **Honda Jazz**
 Year : **2016**
 Chassis No : **JHMGK5850HX200794**

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,085.20	\$ 730.60	1,085.20 DDV
2	Tailgate logo	1	\$ 86.20	\$ 24.80	86.20 NEC
3	Tailgate emblem 'Jazz'	1	\$ 83.40	\$ 32.20	83.40 ✓
4	Tailgate inner lock	1	\$ 389.20	\$ 211.90	389.20 JMV
5	Tailgate inner lock striker	1	\$ 48.90	\$	48.90 NDX
6	Tailgate outer chrome garnish	1	\$ 469.20	\$ 234.40	469.20 BRV
7	Tailgate lamp	2	\$ 583.20	\$	1,166.40 NDX
8	Tailgate weatherstrip	1	\$ 286.30	\$ 138.00	286.30 TNV
9	Tailgate inner trim board	1	\$ 486.20	\$ 285.90	486.20 BRV
10	Tailgate inner handle	1	\$ 105.20	\$	105.20 NDX
11	Tailgate buzzer	1	\$ 286.40	\$ 150.00	286.40 BRV
12	Tailgate antenna sensor	1	\$ 389.40	\$ 180.50	389.40 BRV
13	Tailgate no plate lamp	2	\$ 102.30	\$	204.60 NDX
14	Tailgate solenoid switch	1	\$ 367.50	\$	367.50 NSX
15	Tailgate windscreen moulding	1	\$ 205.30	\$	205.30 ✓ NEC
16	Tailgate windscreen wiper motor	1	\$ 423.50	\$	423.50 NDX
17	Rear bumper	1	\$ 1,064.30	\$ 721.10	1,064.30 BRV
18	Rear bumper side retainer	2	\$ 26.00	\$ 143.60	52.00 ✓ NEC
19	Rear bumper bracket	2	\$ 103.50	\$	207.00 NSX
20	Rear bumper reflector garnish (side)	2	\$ 286.40	\$ 310.00	572.80 BRV
21	Rear end panel	1	\$ 1,045.80	\$ 460.00	1,045.80 DDV
22	Rear end panel top garnish	1	\$ 256.30	\$ 180.00	256.30 BRV
23	Spare tyre panel	1	\$ 986.40	\$ 897.30	986.40 DDV
24	Spare tyre panel top board	1	\$ 250.00	\$	250.00 NSX
25	Spare tyre panel insulator	1	\$ 269.10	\$ 150.00	269.10 ✓ NEC
26	Spare tyre panel sponge box	1	\$ 486.30	\$ 230.00	486.30 BRV
27	Taillamp Rh	1	\$ 853.40	\$ 833.50	853.40 BRV
28	Taillamp lower bracket Rh	1	\$ 145.60	\$	145.60 NSX
29	Taillamp base panel Rh	1	\$ 465.80	\$ 158.00	465.80 DDV
30	Taillamp Lh	1	\$ 853.40	\$ 833.50	853.40 BRV
31	Taillamp lower bracket Lh	1	\$ 145.60	\$	145.60 NSX
32	Taillamp base panel Lh	1	\$ 465.80	\$ 158.00	465.80 DDV
33	Rear fender Rh	1	\$ 986.20	\$ 559.20	986.20 DDV
34	Rear fender inner trim Rh	1	\$ 473.50	\$ 258.40	473.50 TNV
35	Rear fender inner cowl	1	\$ 146.20	\$	146.20 NDX

36	Rear fender quarter glass moulding	RH	1	\$	103.50	\$ 89.60	103.50	NEC
37	Rear fender air vents		1	\$	84.00	\$	84.00	NDX
38	Rear fender Lh		1	\$	986.20	\$	986.20	NDX
39	Rear fender inner trim Lh		1	\$	473.50	\$ 258.40	473.50	BRV
40	Rear door Rh		1	\$	957.60	\$	957.60	Cut RX
41	Rear door lock Rh		1	\$	463.50	\$	463.50	NDX
				Parts Sub Total :	\$	19,111.90		
				20% Discount	\$	3,822.38		
				PARTS TOTAL :	\$	15,289.52		

@ 20% 8,341.80
1,668.36
6,673.44

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Tailgate sealant	1	\$ 100.00	\$ 30.00 100.00	NEC
3	Tailgate outer chrome garnish clips	1	\$ 50.00	\$ 20.00 50.00	NEC
4	Tailgate lamp seal	1	\$ 60.00	\$ 60.00	NNX
5	Tailgate lamp clips	1	\$ 50.00	\$ 50.00	X
6	Tailgate inner trim board clips	1	\$ 50.00	\$ 20.00 50.00	NEC
7	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00 100.00	NEC
8	Tailgate windscreen clips	1	\$ 50.00	\$ 20.00 50.00	NEC
9	Tailgate windscreen inner seal	1	\$ 60.00	\$ 30.00 60.00	NEC
10	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ 80.00	NNX
11	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC
12	Rear bumper reflector garnish clips	1	\$ 50.00	\$ 50.00	NNX
13	Rear end panel sealant	1	\$ 100.00	\$ 30.00 100.00	NEC
14	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	NEC
15	Spare tyre panel sealant	1	\$ 100.00	\$ 30.00 100.00	NEC
16	Taillamp seal	2	\$ 60.00	\$ 40.00 120.00	NEC
17	Taillamp clips	2	\$ 50.00	\$ 20.00 100.00	NEC
18	Rear fender sealant	RH 1 2	\$ 100.00	\$ 30.00 200.00	NEC
19	Rear fender inner trim clips	2	\$ 50.00	\$ 40.00 100.00	NEC
20	Rear fender inner cowling clips Rh	1	\$ 50.00	\$ 50.00	NNX
21	Rear fender quarter glass sealant	RH 1 2	\$ 100.00	\$ 30.00 200.00	NEC
22	Rear fender quarter glass clips	2	\$ 50.00	\$ 100.00	NNX
23	Rear fender quarter glass inner seal	RH 1 2	\$ 60.00	\$ 20.00 120.00	NEC
24	Rear fender quarter glass primer & cleaner	2	\$ 80.00	\$ 160.00	NNX
25	OPC seal	1	\$ 60.00	\$ 60.00	NEC
26	Reverse sensor	1	\$ 250.00	\$ 200.00 250.00	SC
27	Reverse camera	1	\$ 480.00	\$ 480.00	NDX
28	Rear number plate w/casing	1	\$ 80.00	\$ 50.00 80.00	DP
SPECIAL NETT TOTAL :				\$ 3,050.00	

770.00

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 70.00	100.00
2	R&R rear windscreen	\$ 120.00	250.00
3	R&R rear fender quarter glass Lh and RH	\$ 60.00	500.00
4	R&R reverse sensor	\$ 60.00	100.00
5	R&R reverse camera	\$	100.00
6	R&R rear door component	\$	100.00
7	Mount bench work	\$	350.00
8	Rear Chasis alignment	\$	300.00
9	R&R upholstery	\$	300.00
10	Check wiring	\$ 30.00	120.00
11	Diagnostic & reset fault code	\$	300.00
12	Panel beating	\$ 1200.00	2,000.00
13	Rust proofing	\$	150.00
14	Spray painting	\$ 1200.00	2,000.00
LABOUR TOTAL :		\$	6,670.00

Survey Resurvey
 13/7/2021 15/7/2021
 140 hrs 1525 hrs
 Taim M. Taim M.

Lump sum repair
 Repair days 12

LABOUR TOTAL : \$ 6,670.00
 2,740.00
 PARTS TOTAL : \$ 15,289.52
 SPECIAL NETT TOTAL : \$ 3,050.00
 LABOUR TOTAL : \$ 6,670.00
 GRAND TOTAL : \$ 25,009.52

Parts 6,673.44
 SN 770.00
 Labour 2,740.00
 10,183.44
 @ 20% 2036.69
 8,146.75

OR L/S 8150/2

Taim M.
 23/7/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: