



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHAI			Ref: CC4/ASM21007563/Bpa3q2 Date: 24/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6161L	Veh. Inspected	SJY 4619P
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03AUD	Excess (\$)	0.00
	Assign From		Assign Date	12/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 6 2.0	c.c	1999
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JM6GH10F190121239	Colour	GREY
	Odometer	-	Steering	JAMMED
	Brakes	JAMMED	Modification	SPORTS RIM
	General	POOR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	MICHELIN	5 mm
	L/H Front Tyre	205/60 R16	MICHELIN	5 mm
	R/H Rear Tyre	205/60 R16	MICHELIN	5 mm
	L/H Rear Tyre	205/60 R16	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/05/2021	Inspection Date	14/07/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	