

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Hyundai

Elantra

Vehicle Number : SKE3750S (DOA 08.07.2021)

Quantity	Description	Repairer's Estimate
	FRONT	
1	Front LH door replace	\$1,157.00 — DD
1	Front LH door lock	\$189.00 — Jam
1	Front LH door trim board	\$635.80 — BR
1	Front LH door hinge (upper & lower) (LH front)	\$90.00 — BT
1	Front LH door window regulator	\$250.40 — BT
1	Rear LH door	\$1,349.50 — DD
1	Rear LH door trim board	\$553.00 — BR
1	Front LH door hinge (upper & lower) (LH rear)	\$90.00 — BT
1	Front & Rear Rim (LH)	\$600.00 — CUT
1	LH Headlamp	\$693.70 — BR
1	Front LH Fender	\$445.00 — DD
1	Front LH Fender liner	\$92.00 — TN
1	Front Bumper	\$474.60 — BR
1	Front LH Absorber	\$312.00 — BT
	LABOUR & MISC	
1	Checking of wiring, lighting and resetting	\$300 30—
1	Remove and refit rear undercarriage	\$500 100—
1	Wheel alignment	\$100 —
1	Remove and replace damaged parts	\$800 X
1	Apply undercoating on repaired and replaced panel	\$800 X
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,500 1000—
1	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000 —
	Total Repair Cost :	\$11,932

Stere (LKK)
13/7/21

w/P
L/S

Resurvey After Spray
6 days

(4K limit repair)