

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /ONG JIAN DE Reg No/Reg Date SMH5748Y / 28/01/201 Date In/Mileage / 23457 Chassis No KNAF3416MK5024748 Engine No G4FGJH713608 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	12/07/2021/ 19:21	BLE	261 / Edwin Caina	35995		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000				1-5 X 400			2000.00
RENEW (FR PORTION) FR BUMPER , BONNET & FR SUPPORT							600
REPAIR LHF FENDER & RHF FENDER							
E PNT88000				4.5 X 400			4000.00
RENEW RR BUMPER , RR END PNL & BOOTLID							1800
REPAIR RR FLR PNL , LHR FENDER , RHR FENDER , RR CHASSIS & LHR DOOR							
E PNT98000				6 X 350			4200.00
RESPRAY FRT BUMPER , BONNET , LHF FENDER , RHF FENDER ,							2100
RR BUMPER , RR END PNL , RR FLR PNL , LHR FENDER , RHR FENDER ,							
RR CHASSIS , LHF DOOR , RHF DOOR & LHR DOOR							
E PNT88000							100.00
REMOVE & REFIT AC COND & RADIATOR							80.00
M SUNDRY							
TOP UP AC GAS							120.00
E PNT88000							120.00
REMOVE & REFIT BOOTLID COMPONENT							120.00
E PNT88000				(photo)			30.00
REMOVE & REFIT RR FLR BOARD , TRIM , CARPET & SEAT							
A 54900099							120.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							
SUPPLY FR NUMBER PLATE WITH CASING BR							50.00
M SUNDRY							
SUPPLY RR NUMBER PLATE WITH CASING							80.00
E PNT88000							220.00
TO RENEW REVERSE SENSOR							
M SUNDRY							
SUPPLY REVERSE SENSOR BR							40 80.00
M SUNDRY							
APPLY ANTI CORROSION ON AFFECTED AREAS							40 80.00
M SUNDRY							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /ONG JIAN DE Reg No/Reg Date SMH5748Y / 28/01/201 Date In/Mileage / 23457 Chassis No KNAF3416MK5024748 Engine No G4FGJH713608 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	12/07/2021/ 19:21	BLE	261 / Edwin Caina	35995			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
SUPPLY BODY PNL SEALANT								40.00
M SUNDRY								
SUPPLY C&C BADGE								30.00
M SUNDRY								
Sundries								
M	COVER-FR BUMPER	1.00	633.00	20.00	506.40			
M	GRILLE-FRONT BUMPER	1.00	262.00	20.00	209.60			
M	GRILLE ASSY-RADIATOR	1.00	328.00	20.00	262.40			
M	ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20			
M	STIFFNER-FR BPR LWR	1.00	114.00	20.00	91.20			
M	BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60			
M	BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60			
M	PANEL ASSY-HOOD	1.00	1502.00	20.00	1201.60			
M	BEAM COMPLETE-FR BUMPER	1.00	497.00	20.00	397.60			
M	CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00			
M	ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60			
M	LOGO ASSY-KIA SUB	1.00	32.00	20.00	25.60			
M	EMBLEM-CERATO	1.00	28.00	20.00	22.40			
M	COVER-RR BUMPER	1.00	651.00	20.00	520.80			
M	COVER-RR BUMPER LWR	1.00	241.00	20.00	192.80			
M	COVER-RR BUMPER UNDER, LH	1.00	33.00	20.00	26.40			
M	COVER-RR BUMPER FOG LAMP, LH	1.00	19.00	20.00	15.20			
M	COVER-RR BUMPER FOG LAMP, RH	1.00	19.00	20.00	15.20			
M	LAMP ASSY-SIDE T/SIGNAL, LH	1.00	181.00	20.00	144.80			
M	LAMP ASSY-SIDE T/SIGNAL, RH	1.00	181.00	20.00	144.80			
M	EXTN WIRING ASSY-BWS	1.00	207.00	20.00	165.60			
M	BEAM-RR BUMPER	1.00	318.00	20.00	254.40			
M	BRACKET-RR BEAM UPR MTG, RH	1.00	9.00	20.00	7.20			
M	BRACKET-RR BEAM UPR MTG, LH	1.00	9.00	20.00	7.20			
M	BRACKET-RR BEAM LWR, CTR	1.00	6.00	20.00	4.80			
M	BRACKET-RR BEAM LWR MTG	1.00	6.00	20.00	4.80			
M	ANTENNA ASSY-SMARTKEY	1.00	46.00	20.00	36.80			
M	STAY-RR BUMPER LH	1.00	65.00	20.00	52.00			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /ONG JIAN DE Reg No/Reg Date SMH5748Y / 28/01/201 Date In/Mileage / 23457 Chassis No KNAF3416MK5024748 Engine No G4FGJH713608 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	12/07/2021/ 19:21	BLE	261 / Edwin Caina	35995
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M STAY-RR BUMPER RH	BT	1.00	65.00	20.00	52.00
M COVER-RR BUMPER UNDER, RH	xnn	1.00	33.00	20.00	26.40
M BRACKET ASSY-RR BPR SIDE UPR, L	xnn	1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR, R	xnn	1.00	31.00	20.00	24.80
M PANEL ASSY-TRUNK LID	00	1.00	1297.00	20.00	1037.60
M HINGE ASSY-TRUNK LID, LH	xnn	1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID, RH	xnn	1.00	97.00	20.00	77.60
M PANEL ASSY-BACK	00 (photo)	1.00	324.00	20.00	259.20
M TRIM ASSY-RR TRANSVERSE	(CRU)	1.00	41.00	20.00	32.80
M MAT ASSY-LUGGAGE COVERING	xnn	1.00	211.00	20.00	168.80
M W/STRIP-TRUNK LID OPNG	GRU	1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID	BT	1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID	BT	1.00	40.00	20.00	32.00
M LAMP ASSY-REAR COMB INSIDE, LH	xnn	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE, RH	xnn	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE, LH	GR	1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE, RH	CUT	1.00	675.00	20.00	540.00
M LAMP ASSY-CENTER GARNISH	xnn	1.00	690.00	20.00	552.00
M FILM-ANTI CHIPPG RH	NEC	1.00	27.00	20.00	21.60
M FILM-ANTI CHIPPG LH	NEC	1.00	27.00	20.00	21.60

13/7/21, 3:00pm

Steve (LKK) 00-NA M

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

Confirm & accepted by Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on **Nett 21004.00** **21,004.00**
1470.28
Total Payable 22,474.28

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.