



AIG-00 (REVERT)
SURVEY: 13/6/21
LKK - STEVE

VEHICLE NO : SMH 5748Y

MODEL : KIA/CERATO 1.6 A EX

WIP : 35995

Material	:	\$	<u>9,240.00</u>
Labour	:	\$	<u>8,810.00</u>
Sub-Total	:	\$	<u>18,050.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>18,050.00</u>
GST 7%	:	\$	<u>1,263.50</u>
Grand Total	:	\$	<u>19,313.50</u>
Finalise By/Date : <u>Army ON 19/08/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 18 WORKING DAYS + 6 days (3 wk. ends)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /ONG JIAN DE Reg No/Reg Date SMH5748Y / 28/01/2019 Date In/Mileage 12/07/2021/ 23457 Chassis/Package KNAF3416MK502474E /KC17P Engine No G4FGJH713608 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK
13/07/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	19/08/2021/ 08:41	BLE	884 / Lauro Songcuan	35995

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER & BONNET				600.00 ✓
E PNT88000 RENEW REAR BUMPER, REAR END PANEL & BOOTLID				1800.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER, BONNET, REAR BUMPER, REAR END PANEL, LH REAR FENDER & REAR FLOOR PANEL				2100.00 ✓
E PNT88000 REMOVE & REFIT BOOTLID COMPONENTS				120.00 ✓
E PNT88000 REMOVE & REFIT REAR FLOOR BOARD, TRIM, CARPET & SEAT				120.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00 ✓
E PNT88000 RENEW REVERSE SENSOR				80.00 ✓
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00 ✓
M SUNDRY SUPPLY BODY PANEL SEALANT				40.00 ✓
M SUNDRY SUPPLY C&C BADGE				40.00 ✓
M SUNDRY SUNDRIES				30.00 ✓
S SPECIALISTJOB SUPPLY ONE PC OF FRONT LICENSE PLATE WITH PLASTIC FRAME MODEL: CERATO				50.00 ✓
A 13900099 REMOVE & REFIT FUEL TANK ASSY				200.00 ✗
E PNT88000 REPLACE FLOOR PANEL, BOTH REAR QUARTER PANEL AND REPAIR BOTH CHASSIS				2200.00 ✗

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /ONG JIAN DE Reg No/Reg Date SMH5748Y / 28/01/2019 Date In/Mileage 12/07/2021/ 23457 Chassis/Package KNAF3416MK502474E /KC17P Engine No G4FGJH713608 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK
13/07/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	19/08/2021/ 08:41	BLE	884 / Lauro Songcuan	35995
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REMOVE & REFIT REAR WINDSCREEN GLASS				240.00 X
M SUNDRY	SUPPLY REAR WINDSCREEN GLASS SEALANT				80.00 X
E PNT98000	SPRAY PAINT BOOT LID & RH REAR QUARTER PANEL				700.00 X
S SPECIALISTJOB	SUPPLY ONE SET FOR REVERSE SENSOR (CERATO)				220.00 ✓
X COVER-FR BUMPER		1.00	633.00	20.00	506.40 ✓
X GRILLE-FRONT BUMPER		1.00	262.00	20.00	209.60 ✓
X PANEL ASSY-HOOD		1.00	1502.00	20.00	1201.60 ✓
X ORNAMENT-KIA NO.115		1.00	32.00	20.00	25.60 ✓
X LOGO ASSY-KIA SUB		1.00	32.00	20.00	25.60 ✓
X EMBLEM-CERATO		1.00	28.00	20.00	22.40 ✓
X COVER-RR BUMPER		1.00	651.00	20.00	520.80 ✓
X COVER-RR BUMPER LWR		1.00	241.00	20.00	192.80 ✓
X COVER-RR BUMPER FOG LAMP,LH		1.00	19.00	20.00	15.20 ✓
X LAMP ASSY-SIDE T/SIGNAL,LH		1.00	181.00	20.00	144.80 ?
X BEAM-RR BUMPER		1.00	318.00	20.00	254.40 ✓
X BRACKET-RR BEAM UPR MTG,LH		1.00	9.00	20.00	7.20 ?
X BRACKET-RR BEAM LWR,CTR		1.00	6.00	20.00	4.80 ?
X STAY-RR BUMPER RH		1.00	65.00	20.00	52.00 ?
X PANEL ASSY-TRUNK LID		1.00	1297.00	20.00	1037.60 ✓
X PANEL ASSY-BACK		1.00	324.00	20.00	259.20 ✓
X TRIM ASSY-RR TRANSVERSE		1.00	41.00	20.00	32.80 ?
X LATCH ASSY-TRUNK LID		1.00	112.00	20.00	89.60 ?
X STRIKER ASSY-TRUNK LID		1.00	40.00	20.00	32.00 ?
X LAMP ASSY-REAR COMB OUTSIDE,LH		1.00	675.00	20.00	540.00 ✓
X LAMP ASSY-REAR COMB OUTSIDE,RH		1.00	675.00	20.00	540.00 ?
X FILM-ANTI CHIPPG RH		1.00	27.00	20.00	21.60 ?
X FILM-ANTI CHIPPG LH		1.00	27.00	20.00	21.60 ✓
X GARNISH-RADIATOR GRILLE		1.00	38.00	20.00	30.40 X
X COVER-FR BUMPER FOG LAMP,LH		1.00	15.00	20.00	12.00 X

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /ONG JIAN DE Reg No/Reg Date SMH5748Y / 28/01/2019 Date In/Mileage 12/07/2021/ 23457 Chassis/Package KNAF3416MK502474E /KC17P Engine No G4FGJH713608 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK
13/07/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	19/08/2021/ 08:41	BLE	884 / Lauro Songcuan	35995

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X COVER-RR BUMPER FOG LAMP,RH ?	1.00	19.00	20.00	15.20
X TRIM ASSY-TRUNK LID → Supp.	1.00	202.00	20.00	161.60
X W/STRIP-TRUNK LID OPNG ?	1.00	100.00	20.00	80.00
X PROTECTOR-HEAT REAR	1.00	136.00	20.00	108.80
X PANEL ASSY-REAR FLOOR,RR	1.00	219.00	20.00	175.20
X REINF-RR SPARE TIRE WELL CROSS	1.00	41.00	20.00	32.80
X HOOK-TOWING	1.00	16.00	20.00	12.80
X REINF-TOWING HOOK	1.00	14.00	20.00	11.20
X PANEL ASSY-QUARTER OUTER,RH	1.00	1349.00	20.00	1079.20
X PANEL ASSY-QUARTER OUTER,LH	1.00	1349.00	20.00	1079.20
X PANEL ASSY-RR COMB LAMP HSG,RH	1.00	135.00	20.00	108.00
X PANEL ASSY-RR COMB LAMP HSG,LH	1.00	139.00	20.00	111.20
X PAD-WINDSHIELD GLASS	1.00	2.00	20.00	1.60
X FASTENER	10.00	1.00	20.00	8.00
X STAY-RR BUMPER LH ?	1.00	65.00	20.00	52.00
X CLIP → Supp.	10.00	2.00	20.00	16.00
X SILENCER,FLOOR	2.00	13.00	20.00	20.80
X ABSORBER-FRONT BUMPER ENERGY ?	1.00	84.00	20.00	67.20
X GRILLE ASSY-RADIATOR	1.00	328.00	20.00	262.40
X ANTENNA ASSY-SMARTKEY → Supp.	1.00	46.00	20.00	36.80

Z TEXT

AIG OD CLAIM - REVERT
 DOA: 10/07/2021
 SURVEY: STEVE (LKK) 13/07/2021
 18 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	9,240.00	Nett	18,050.00
Labour	8,310.00	7% GST on	1263.50
Standard Menu	0.00		
Specialist Job	270.00	Total Payable	19,313.50
Diagnostics Job	0.00		
Sundry/Others	230.00		
Total(w/o GST)	18,050.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.




CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMH 5748 Y**

<u>Materials</u>		<u>Cost \$</u>
1	Garnish- Radiator Grille	38.00 ✓ BR
2	Cover- FR Bumper Fog Lamp, LH	15.00 ✓ CVT
3	Trim Assy- Trunk Lid	202.00 ✓ CRV
4	Protector- Heat Rear	136.00 ✓ BT
5	Panel Assy- Rear Floor, RR	219.00 ✓ DD
6	Reinf- RR Spare Tire Well Cross	41.00 ✓ nec
7	Hook- Towing	16.00 ✓ nec
8	Reinf- Towing Hook	14.00 ✓ nec
9	Panel Assy- Quarter Outer, RH	1,349.00 ✓ DD
10	Panel Assy- Quarter Outer, LH	1,349.00 ✓ DD
11	Panel Assy- RR Comb Lamp Hsg, RH	135.00 ✓ JD
12	Panel Assy- RR Comb Lamp Hsg, LH	139.00 ✓ DD
13	Pad- Windshield Glass	2.00 ✓ nec
14	Fastener (10 pcs)	10.00 ✓ nec
15	Clip (10 pcs)	20.00 ✓ nec
16	Silencer, Floor (2 pcs)	26.00 ✓ nec
17	Antenna Assy- Smartkey	46.00 ✓ BR
		<u>3,757.00</u>
20% Discount		<u>751.40</u>
		<u>3,005.60</u>
<u>Labour</u>		
1	Remove & Install Fuel Tank Assy	200.00 ✓
2	Replace Floor Panel, Both Rear Qtr Panel, Repair Both Chassis	2,200.00 ✓
3	Remove & Refit Rear Windscreen Glass	240.00 ✓
4	Supply Rear Windscreen Glass Sealant	80.00 ✓
5	Spray Paint Boot Lid & RH Rear Quarter Panel	700.00 ✓
		<u>3,420.00</u>
Labour & Materials		6,425.60
7% GST		<u>449.79</u>
Total		<u>6,875.39</u>

Thank You.


 LARRY SONG CHAN
 CYCLE & CARRIAGE
 PANDAN GARDENS

CAR NO: SMH 57484

WIP: 35995

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Absorber Front Bumper Energy	? / SUPP		RR	
2	Fog Lamp Cover LH	? / SUPP		CUT	
3	Garnish Radiator Grille	? / SUPP		RR	
4	Cover Rear Bumper Fog Lamp RH	? / SUPP		CUT	
5	Lamp Assy - Side T/SIGNAL LH	? / SUPP	(Bump)	RR	
6	EXTN Wiring Assy BWS	? / SUPP		X	
7	Bracket RR Beam UPR MTG LH	? / SUPP		RR	
8	Bracket RR Beam LWR CTR	? / SUPP		RR	
9	Stay RR Bumper LH	? / SUPP		RT	Steve
10	Stay RR Bumper RH	? / SUPP		RT	15/7/21
11	Trim Assy RR Transverse	? / SUPP		CRU	
12	Mat Assy Luggage Covering	? / SUPP		X	
13	W/Strip-Trunk LID ORNG	? / SUPP		CRU	
14	Lamp Assy Rear COMB Outside RH	? / SUPP		CRU	
15	Film Anti-Chipping RH	? / SUPP		ACC	
16	Trim Trunk LID	? / SUPP		CRU	
17	Heat Protector	? / SUPP		RT	
18	Hook	? / SUPP		ACC	
19	Heck Extension (Reinforcement)	? / SUPP		ACC	
20	Floor Extension Cross	? / SUPP		ACC	

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATO 1.6 A EX

SURVEYOR: STEVE LKK

CAR NO: 54H 57489WIP: 35995

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1 ✓	Floor Panel	? / SUPP		✓ <u>OK</u>	} Steve 15/7/21 (photo)
2 ✓	QTR Panel LH	? / SUPP		✓ <u>OK</u>	
3 ✓	QTR Panel RH	? / SUPP		✓ <u>OK</u>	
4 ✓	Panel Rear Lamp LH	? / SUPP		✓ <u>OK</u>	
5 ✓	Panel Rear Lamp RH	? / SUPP		✓ <u>OK</u>	
6 ✓	Spacer Pad	? / SUPP		✓ <u>OK</u>	
7 ✓	Clip Rear Bumper	? / SUPP		✓ <u>OK</u>	
8 ✓	Clip Trim Luggage	? / SUPP		✓ <u>OK</u>	
9 ✓	Covermet Rear Bumper	? / SUPP		✓ <u>OK</u>	
10 ✓	Windscreen Spacer (Pad)	? / SUPP		✓ <u>OK</u>	
11 ✓	R/I Fuel Tank	? / SUPP			
12 ✓	Repair Both Chassis	? / SUPP			
13 ✓	Replace Floor Panel →	? / SUPP	\$2200	✓	
14 ✓	Replace Both Rear QTR Panel (S.S)	? / SUPP	\$2500	✓	
15 ✓	R/I Rear Windscreen	? / SUPP	\$700	✓	
16 ✓	Respray Boot Lid, Rear RH Fender X2	? / SUPP	\$80	✓	
17 ✓	Supply of Windscreen glass and cut	? / SUPP			
18 ✓	Antenna H95y Smart Key	? / SUPP		✓ <u>OK</u>	
19		? / SUPP			
20	Add repair days 7 (total 18)	? / SUPP		✓	

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CeratoSURVEYOR: Steve Lick

CAR NO: SMH 5748Y

WIP: 35995

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Latch Trunk Lid	? / SUPP		✓ BT	
2	Styker Assy Trunk Lid	? / SUPP		✓ BT	Sten 21/7/21
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Cerato

SURVEYOR: Steve CLK



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



IBU-SMK

9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0251

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0192

OS Ver.

Android 10



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..



VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



IBU-SMK



IBU-BCM

9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
CLU	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0251

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0192

OS Ver.

Android 10