

WILLIAM LEE CAR AIRCON ENGINEERING

61 UBI AVENUE 2 #08-04B

AUTOMOBILE MEGAMART SINGAPORE 408898

TEL : 6382 1006 FAX : 6383 4088

Vehicle No. SFU 5822 E

Parts and Labour Assessment

Description of part

PARTS (LIST ITEMS)

	Qty	Cost	
1 REAR TAILGATE / <i>DD</i>	1	1,540.30	1152 /
2 REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM / <i>REC</i>	1	96.10	85 /
3 REAR TAILGATE 'LOGO' EMBLEM / <i>REC</i>	1	115.30	60 /
4 REAR TAILGATE HINGES L/R X <i>nn</i>	2	226.00	
5 REAR TAILGATE DAMPER L/R X <i>nn</i>	2	540.00	
6 REAR TAILGATE REFLECTOR L/R <i>(CRH)</i> / <i>GR</i>	2	928.20	393 /
7 REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R X <i>nn</i>	2	159.80	
8 REAR TAILGATE WINDSCREEN MOULDING / <i>REC</i>	1	242.90	197 /
9 REAR TAILGATE WINDSCREEN GLASS / <i>GR</i>	1	1,977.60	1051 /
10 REAR TAILGATE WIPER ARM X <i>nn</i>	1	284.80	
11 REAR TAILGATE WIPER ARM BLADE X <i>nn</i>	1	98.60	
12 REAR TAILGATE WIPER ARM COVER X <i>nn</i>	1	55.60	
13 REAR TAILGATE WIPER MOTOR X <i>nn</i>	1	855.00	
14 REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER) X <i>nn</i>	2	192.00	
15 REAR TAILGATE OUTER GARNISH X <i>nn</i>	1	364.80	
16 REAR TAILGATE OPENER BUTTON SENSOR X <i>nn</i>	1	285.00	
17 REAR TAILGATE NUMBER PLATE LAMP L/R X <i>nn</i>	2	188.30	
18 REAR TAILGATE INNER PULL HANDLE X <i>nn</i>	1	98.30	
19 REAR TAILGATE INNER UPHOLSTERY TRIM BOARD X <i>nn</i>	1	752.80	
20 REAR TAILGATE RUBBER GUIDE STOPPER L/R X <i>nn</i>	2	68.80	
21 REAR TAILGATE WEATHER STRIP / <i>CRU</i>	1	482.80	389 /
22 REAR TAILGATE MECHANISM LOCK / <i>BT/jammed</i>	1	535.60	318 /
23 REAR TAILLAMP L/R <i>(CRH)</i> / <i>GR</i>	2	1,122.20	437 /
24 REAR TAILLAMP INNER PANEL RH / <i>DD</i>	1	678.20	285 /
25 REAR TAILLAMP LOWER BRACKET L/R X <i>nn</i>	2	162.80	
26 REAR FENDER RH / <i>DD</i>	1	1,227.40	/
27 REAR FENDER GLASS MOULDING RH X <i>nn</i>	1	414.90	
28 REAR FENDER INNER TRIM BOARD L/R / <i>CRU (CRH)</i>	2	1,218.00	609 /
29 REAR FENDER INNER SHIELD RH X <i>nn</i>	1	128.00	
30 REAR FENDER AIR VENT RH / <i>CRU</i>	1	188.00	86 /

31	REAR FENDER PROTECTOR RH	X	nn	1	312.10	
32	REAR SLIDING DOOR RAIL COVER RH	X	nn	1	362.20	
33	REAR SLIDING DOOR RAIL RH	X	nn	1	382.90	
34	REAR BUMPER	/	CR4	1	1,127.20	788/
35	REAR BUMPER CENTRE PROTECTOR	/	CUT	1	235.40	209/
36	REAR BUMPER END SEAL COVER L/R	/	(RH) - CUT	21	662.30	216/
37	REAR BUMPER REFLECTOR L/R	/	(RH) - GR	21	194.80	93/
38	REAR BUMPER SIDE PROTECTOR GARNISH L/R	X	nn	2	382.50	
39	REAR BUMPER SIDE PROTECTOR COVER L/R	X	nn	2	482.80	
40	REAR BUMPER SIDE RETAINER L/R	/	GR	2	314.70	130/
41	REAR BUMPER TOW HOOK COVER	X	nn	1	45.00	
42	REAR END PANEL TOP GARNISH	/	CR4	1	362.00	208/
43	REAR END PANEL BUZZER SENSOR	X	nn	1	256.10	
44	REAR END PANEL KEY ANTENNA SENSOR	X	nn	1	272.80	
45	REAR END PANEL	X	R	1	782.50	
46	REAR EXHAUST SILENCER BOX	X	nn	1	1,462.70	

7933.40
- 25%
5950.05

Percentage discount 15%

	\$	22,866.10
	\$	3,429.92
Sub-total	\$	19,436.19

SPECIAL NETT ITEMS

1	REAR TAILGATE INNER UPHOLSTERY TRIM BOARD CLIPS - SET	1	80.00	X nn
2	REAR TAILGATE OUTER GARNISH CLIPS - SET	1	80.00	X nn
3	REAR TAILGATE REVERSE CAMERA	1	900.00	X nnn
4	REAR TAILGATE WINDSCREEN SEALANT	1	nec 160.00	40/
5	REAR TAILGATE NUMBER PLATE	1	30.00	X nn
6	REAR TAILGATE NUMBER PLATE HOLDER	1	60.00	X nn
7	REAR TAILLAMP CLIPS L/R - SET	1	80.00	X nn
8	REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	nec 200.00	20/
9	REAR FENDER INNER SHIELD CLIPS L/R - SET	2	160.00	X nn
10	REAR FENDER GLASS SEALANT L/R - SET	2	nec 240.00	30/
11	REAR BUMPER CLIPS - SET	1	nec 100.00	30/
12	REAR BUMPER END SEAL COVER CLIPS L/R - SET	2	nec 120.00	10/
13	REAR BUMPER REVERSE SENSOR	1	650.00	X nn
14	REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	nec 80.00	10/

140

Sub-total	\$	2,940.00
------------------	-----------	-----------------

LABOUR

- | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|--------|
| 1 To provide towing charge(3 trips), scene-wkshop,wkshop-idac.idac-wkshop. | 240.00 | 80 ✓ |
| 2 To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor. | 300.00 | 30 ✓ |
| 3 To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet. | 250.00 | 80 ✓ |
| 4 To remove, reinstall Rh fender glass, tailgate windscreen. 120 + 80 | 360.00 | 200 ✓ |
| 5 To reset system after repair works. | 400.00 | X |
| 6 To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. | 2,000.00 | 800 ✓ |
| 7 To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | 2,600.00 | 1800 ✓ |
| 8 To apply anti-rust chemical on repaired and replaced panel. | 180.00 | 30 ✓ |

2220

Labour Total \$ 6,330.00

Parts & Labour Total \$ 28,706.19

Best Regards,

Steve (LKK)
13/7/21

WL PL
LIS

My AC sy
10 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5950.05

NI- 140

L- 2220

8310.05

LIS- 6648.04

= 6650 ✓